Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008619/AES3Q2

Date: 16/04/2021

REFERENCE

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 4215280918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA7633H

 Make & Model:
 TOYOTA HIACE, 2.5 (M)
 Engine No:
 2KD1647936

 Reg. Date:
 16/04/2008 (Man. Year: 2007)
 Chassis No:
 KDH2000079892

 Colour:
 Silver
 Odometer:
 692037 km

Engine Capacity: 2494 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Condor 6 mm Rear Left Side: Condor 6 mm
Front Right Side: Condor 6 mm Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,969.80	2,851.87	1,117.93	28.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	1,010.00	500.00	33.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,479.80	3,861.87	1,617.93	29.53
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,479.80	3,050.00	2,429.80	44.34
+ GST 7.00/7.00% (S\$)	383.59	213.50	170.09	44.34
Nett Amount (S\$)	5,863.39	3,263.50	2,599.89	44.34
+ Car Rental (7.0 x S\$	120.00/day) (S\$)	840.00		
N	ett Liability (S\$)	4,103.50		
Global Sum	Settlement (S\$)	4.100.00		

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At: J Mart Motor Pte Ltd (HQ)

BLK 5 DEFU LANE 10 #01-578

Singapore 539186

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*RH HEADLAMP	Cracked	825.00 FL	*825.00 FL
1		*RH HEADLAMP CLIP	Necessary	25.00 FL	*25.00 FL
1		*FRT BUMPER	Deformed	595.00 FL	*595.00 FL
1		*FRT BUMPER RH RETAINER	Necessary	198.00 FL	*95.00 FL
1		*FRT BUMPER RH FOG LAMP COVER	Not Necessary	50.00 FL	*- FL
10		*FRT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
1		*FRT RH DOOR	Dented	1,867.90 FL	*1,680.00 FL
1		*AIR CLEANER BOX	Not Necessary	673.00 FL	*- FL
1		*FRT GRILLE	Cracked	485.00 FL	*485.00 FL
5		*FRT GRILLE CLUPS	Necessary	27.50 FL	*27.50 FL
1		*FRT RH CORNER PANEL	Not Necessary	245.00 FL	*- FL
1		*FRT RH STEP GARNISH	Repair	160.00 FL	*- FL
5		*FRT RH STEP GARNISH CLIPS	Not Necessary	25.00 FL	*- FL
1		*FRT RH DOOR STICKER	Necessary	50.00 FS	*30.00 FS
anchise	part. S=SpcN	Nett. L=ListItemDisc.	-		
			Sub Total (S\$)	5,276.40	3,792.50
- List Item Discount on L Items 25.00/25.00% (S\$)				1,306.60	940.63
			Total Parts (S\$)	3,969.80	2,851.87
	1 1 1 1 1 1 1 1 1 5 1 1	1 1 1 1 1 1 10 1 1 1 5 1 1 5	1 *RH HEADLAMP 1 *RH HEADLAMP CLIP 1 *FRT BUMPER 1 *FRT BUMPER RH RETAINER 1 *FRT BUMPER RH FOG LAMP COVER 10 *FRT BUMPER CLIPS 1 *FRT RH DOOR 1 *AIR CLEANER BOX 1 *FRT GRILLE 5 *FRT GRILLE 5 *FRT GRILLE CLUPS 1 *FRT RH CORNER PANEL 1 *FRT RH STEP GARNISH 5 *FRT RH STEP GARNISH CLIPS 1 *FRT RH DOOR STICKER anchise part. S=SpcNett. L=ListItemDisc.	1 *RH HEADLAMP CLIP Necessary 1 *FRT BUMPER Deformed 1 *FRT BUMPER RH RETAINER Necessary 1 *FRT BUMPER RH FOG LAMP COVER Not Necessary 10 *FRT BUMPER CLIPS Necessary 11 *FRT RH DOOR Dented 1 *AIR CLEANER BOX Not Necessary 1 *FRT GRILLE Cracked 5 *FRT GRILLE CLUPS Necessary 1 *FRT RH CORNER PANEL Not Necessary 1 *FRT RH STEP GARNISH Repair 5 *FRT RH STEP GARNISH Repair 5 *FRT RH STEP GARNISH CLIPS Not Necessary 1 *FRT RH STEP GARNISH CLIPS Not Necessary 1 *FRT RH STEP GARNISH CLIPS Not Necessary 1 *FRT RH STEP GARNISH CLIPS Not Necessary 2 **Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)	1 *RH HEADLAMP Cracked 825.00 FL 1 *RH HEADLAMP CLIP Necessary 25.00 FL 1 *FRT BUMPER Deformed 595.00 FL 1 *FRT BUMPER RH RETAINER Necessary 198.00 FL 1 *FRT BUMPER RH FOG LAMP COVER Not Necessary 50.00 FL 10 *FRT BUMPER CLIPS Necessary 50.00 FL 1 *FRT RH DOOR Dented 1,867.90 FL 1 *AIR CLEANER BOX Not Necessary 673.00 FL 1 *FRT GRILLE Cracked 485.00 FL 5 *FRT GRILLE CLUPS Necessary 27.50 FL 1 *FRT RH CORNER PANEL Not Necessary 245.00 FL 1 *FRT RH STEP GARNISH Repair 160.00 FL 5 *FRT RH STEP GARNISH CLIPS Not Necessary 25.00 FL 1 *FRT RH DOOR STICKER Necessary 50.00 FS anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 5,276.40 - List Item Discount on L Items 25.00/25.00% (S\$) 1,306.60

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	600.00	500.00
3	WIRING	New	30.00	30.00
4	TRANSFER DOOR PARTS	New	80.00	80.00
		Gross Labour Cost (S\$)	1,510.00	1,010.00

Report was unsubmitted during this print-out.