



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 2138A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,099.10	-
1	FRONT BUMPER (CONSISTENT)	DISTORTED	665.40	485.20
1	FRONT BUMPER SIDE RETAINER N/S (CONSISTENT)	CRACKED	68.50	68.50
1	FRONT BUMPER FOG LAMP N/S (CONSISTENT)	CRACKED	145.50	145.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	381.20	-
1	HEADLAMP N/S (CONSISTENT)	CRACKED	991.20	688.10
1	FRONT FENDER N/S (CONSISTENT)	DENTED /BENT	866.10	581.10
1	FRONT FENDER INNER SHIELD N/S (CONSISTENT)	DEFORMED / TORN	292.30	188.20
1	SET FRONT FENDER INNER SHIELD CLIPS N/S (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT FENDER 'VVTI' EMBLEM N/S (CONSISTENT)	NECESSARY	65.00	65.00
1	FRONT SHOCK ABSORBER N/S (CONSISTENT)	BENT / TWISTED	692.30	488.10
1	FRONT LOWER ARM N/S (CONSISTENT)	BENT	655.10	585.50
1	FRONT KNUCKLE ARM N/S (CONSISTENT)	BENT	688.50	522.20
1	FRONT KNUCKLE ARM BEARING N/S(CONSISTENT)	NECESSARY	250.00	185.00
1	FRONT DRIVE SHAFT N/S(CONSISTENT)	NOT NECESSARY	1,450.10	-
1	WIPER WASHER TANK (CONSISTENT)	DEFORMED	288.20	211.20
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,299.10	-
	LESS 50% DISCOUNT		-	-2,131.80
			9,947.60	2,131.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT SPORT RIM N/S (SN) (CONSISTENT)	DENTED / BENT	850.00	450.00
1	FRONT TYRE N/S (SN) (CONSISTENT)	SERVICEABLE	200.00	-
			1,100.00	500.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING .		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACE FRONT UNDER CARRIAGE.		180.00	120.00

Report Ref No. CC4/ASM20008623/Upa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER FRONT DOOR MECHANISM .	NOT NECESSARY	80.00	-
	TO SPRAY RUST PROOFING .		100.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT DOOR N/S .		1,000.00	450.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,030.00	1,500.00
<b>GRAND TOTAL</b>			<b>14,077.60</b>	<b>4,131.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,100.00</b>

Report Ref No. CC4/ASM20008623/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.