

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008624/KES3Q2

**Date:** 27/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900254691

**Claimant**  
**Vehicle No :** SML8864D **Insured Vehicle No :** SLF9359H

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 5305181382SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML8864D</b>		
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Engine No:	K9KF649D059792
Reg. Date:	10/06/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00662894724
Colour:	Metallic Silver	Odometer:	141131 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/55R20	Rear Tyre Size:	195/55R20
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,274.91	4,760.15	5,514.76	53.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,250.00	1,570.00	55.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,094.91</b>	<b>6,010.15</b>	<b>7,084.76</b>	<b>54.10</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,800.00</b>		
<b>(\$\$)</b>	13,094.91	4,800.00	8,294.91	63.34
<b>+ GST 7.00/7.00% (\$\$)</b>	916.64	336.00	580.64	63.34
<b>Nett Amount (\$\$)</b>	<b>14,011.55</b>	<b>5,136.00</b>	<b>8,875.55</b>	<b>63.34</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>5,378.00</b>		

### INSPECTION

Date of Assignment: 18/08/2020

Date Inspected: 24/08/2020 Inspected At:

Munich Autocare Pte Ltd (HQ)  
60 Jalan Lam Huat, #02-02/03 Carros  
Centre  
Singapore 7378694

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,152.96 FL	*1,152.96 FL
2	1		*REAR BUMPER LOWER MOULDING	Serviceable	696.24 FL	*- FL
3	1		*REAR BUMPER CENTRE BRACKET	Serviceable	357.84 FL	*- FL
4	1		*REAR BUMPER BRACKET LH	Repair	288.96 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	685.68 FL	*- FL
6	1		*REAR LOGO DIAMOND	Necessary	165.72 FL	*135.80 FL
7	1		*REAR EMBLEM RENAULT	Necessary	130.56 FL	*130.56 FL
8	1		*REAR EMBLEM SCENIC	Necessary	151.44 FL	*126.20 FL
9	1		*TAILGATE OUTER PANEL	Repair	755.40 FL	*- FL
10	1		*TAILGATE OUTER PANEL CHROME	Serviceable	473.16 FL	*- FL
11	1		*TAILGATE TOP SPOILER	Serviceable	383.88 FL	*- FL
12	1		*TAILGATE ASSY	Bent	2,433.84 FL	*1,929.90 FL
13	1		*TAILGATE HINGE LH	Repair	508.80 FL	*- FL
14	1		*TAILGATE HINGE RH	Repair	508.80 FL	*- FL
15	1		*TAILGATE LOCK	Damaged	235.80 FL	*235.80 FL
16	1		*TAILGATE CATCH LOCK	Repair	112.00 FL	*- FL
17	1		*TAILGATE INNER TRIM	Cracked	814.56 FL	*814.56 FL
18	1		*REINFORCEMENT REAR PANEL	Bent	685.50 FL	*685.50 FL
19	1		*REVERSE SENSOR	Serviceable	707.88 FS	*- FS
20	2		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
21	6		*TAILGATE CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,329.02</b>	<b>5,281.28</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,054.11	521.13
<b>Total Parts (\$\$)</b>	<b>10,274.91</b>	<b>4,760.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR SPRAY PAINT TAILGATE, REAR BUMPER, REAR SPOILER & REAR END PANEL	New	1,200.00	500.00
2	LABOUR FOR WELDING & KNOCKING REAR END PANEL AND ALL AFFECTED AREAS	New	1,000.00	500.00
3	TO CHECK WIRING & SYSTEM FUNCTION	New	120.00	20.00
4	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS TO NEW TAILGATE	New	200.00	120.00
5	LABOUR FOR INSTALL REVERSE SENSOR AND REAR IN CAR CAMERA	New	120.00	60.00
6	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	100.00	30.00
7	TO CHECK TAILGATE WATER SEEPAGE	New	80.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>2,820.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >