

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3198C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRT BUMPER GRILLE LH	TO REPAIR SEE LABOUR	93.60	-
	LESS 20% DISCOUNT		-229.16	-210.44
			916.64	841.76
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER GRILLE LH.		300.00	280.00
	SPRAY PAINT CHARGE.		250.00	200.00
			550.00	480.00
	GRAND TOTAL		1,466.64	1,321.76

RECOMMENDED COST OF LUMP SUM REPAIRS		1,050.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC20008625/T1vf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.