

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20008627/T1tf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	31-08-2020 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGY 662A	Veh. Inspected SHB 3780G		
	Policy No.	5081947501-04	Coverage (\$)		0.00
	Claim No.	MT/1100062-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	17/08/2020
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2017
	Chassis No.	KMHLB41UMHU098322	Colou	Ť	YELLOW
	Odometer	491053	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	WEST	LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST	LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST	LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST	LAKE	6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	ident Date 15/08/2020 Inspection Date 17/08/2020			
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a.	ia. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				