



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2965Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	BENT	1,789.90	1,789.90
1	REAR DOOR LWR MOULDING LH	DEFORMED	116.20	116.20
1	REAR WHEEL CAP LH	CUT	346.40	346.40
1	ROCKER PANEL GARNISH LH	DEFORMED	290.00	290.00
	LESS 20% DISCOUNT		-508.50	-508.50
			2,034.00	2,034.00
	<u>NETT ITEMS</u>			
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
1	FUEL TANK LID (PETROL ONLY) (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-11.00	-11.00
			99.00	99.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	480.00
	SPRAYPAINT-RR BUMPER / FENDER ETC.		1,000.00	700.00
	CHECK WIRING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		60.00	30.00
	TRANSFER OF DOOR.		120.00	60.00
			1,920.00	1,300.00
	GRAND TOTAL		4,053.00	3,433.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,433.00

Report Ref No. NS/INC20008628/T1sf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.