

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008638/KRA3Q2

**Date:** 28/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100477724

**Claimant**  
**Vehicle No :** SMR8941H **Insured Vehicle No :** SKQ4970D

Date of Loss: 15/08/2020 Nature of Claim: TP Claim No: 3983253185SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8941H	Engine No:	F3981448B38B15A
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E36070NU32176
Reg. Date:	18/11/2016 (Man. Year: 2016)	Odometer:	45425 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,438.86	1,318.72	1,120.14	45.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,430.00	550.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,418.86</b>	<b>2,748.72</b>	<b>1,670.14</b>	<b>37.80</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,200.00</b>		
<b>(\$\$)</b>	4,418.86	2,200.00	2,218.86	50.21
<b>+ GST 7.00/7.00% (\$\$)</b>	309.32	154.00	155.32	50.21
<b>Nett Amount (\$\$)</b>	<b>4,728.18</b>	<b>2,354.00</b>	<b>2,374.18</b>	<b>50.21</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 18/08/2020

Date Inspected: 18/08/2020 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)  
160 Sin Ming Drive #02-20, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,178.85 FL	*- FL
2	1		*O/S REAR BUMPER SIDE RETAINER	Serviceable	65.75 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*O/S REAR DOOR	Bent / Warped	1,273.85 FL	*1,273.85 FL
5	1		*O/S REAR DOOR WEATHERSTRIP	Necessary	141.40 FL	*141.40 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,709.85</b>	<b>1,465.25</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	270.99	146.53

<b>Total Parts (\$\$)</b>	<b>2,438.86</b>	<b>1,318.72</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ,AFFECTED PARTS	New	800.00	540.00
2	TO APPLY UNDERSEALING	New	80.00	30.00
3	TO REMOVE DOORS FITTINGS	New	100.00	60.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,000.00	800.00
<b>Gross Labour Cost (\$)</b>			<b>1,980.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**