Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008639/UPS3Q2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900116931 Policy No: Claimant SJS546Z Insured Vehicle No: SJZ9229T

Vehicle No:

Date of Loss: Nature of Claim: ΤP 14/08/2020 Claim No: 5178305545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJS546Z Reg No:

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX945405

Chassis No: Reg. Date: 28/07/2009 (Man. Year: 2009) MR053HY9305123728

Colour: Odometer: Silver 172099 km

Engine Capacity: 1497 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15 Front Left Side: Grenlander 5 mm Rear Left Side: Grenlander 5 mm Front Right Side: Rear Right Side: Grenlander 5 mm Grenlander 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,403.85	1,336.50	1,067.35	44.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,460.00	860.00	37.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,723.85	2,796.50	1,927.35	40.80
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	4,723.85	2,200.00	2,523.85	53.43
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/08/2020

Date Inspected: 18/08/2020 Inspected At: Quan De Motor Trading

BLK 1 KAKI BUKIT AVENUE 6 #01-67

AUTOBAY SINGAPORE 417883

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	365.10 FL	*365.10 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	48.20 FL	*- FL
3	1		*REAR BUMPER SPLASH SHIELD RH	Deformed	87.20 FL	*87.20 FL
4	1		*TAILLAMP RH	Cracked	345.10 FL	*345.10 FL
5	1		*REAR FENDER RH	Badly Dented / Bent	766.50 FL	*766.50 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	98.10 FL	*98.10 FL
7	1		*REAR SHOCK ABSORBER RH	Not Necessary	366.50 FL	*- FL
8	1		*REAR HUB BEARING	Not Necessary	315.10 FL	*- FL
9	1		*REAR SPORT RIM RH	Repair	680.00 FL	*- FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$)				3,171.80	1,752.00	
	- List Item Discount on L Items 25.00/25.00% (S\$) 767.95 415.50					
				Total Parts (S\$)	2,403.85	1,336.50
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & REFIX UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	30.00
6	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
7	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	180.00	0.00
8	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	700.00	600.00
9	SPRAY PAINTING	New	850.00	500.00
	Gross Labo	2,320.00	1,460.00	
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >