

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/11120008642/USF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA36767

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MTD / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/8/20 4/5 @ 2850 confirmed with AH Long

(\$ 4,497.95/RED - 61%)

Date/Time, File Pass to?

31/08/2020

1) TYPIST

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum I.B.I.: (\$ \$ 2,850.00 L/S)

TOTAL

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Not Authorised
N/A
19/8/20 3 days

Date: 18/8/2020

Vehicle No: SLH 4443 Z

1	1 PC Front bumper	1155.00	crn / Torn	\$ 1578.60	✓
2	1 PC Front bumper retainer	crn		\$ 73.60	✓
3	1 PC Front side mirror	crn		\$ 988.60	✓
4	1 PC Front fender	R		\$ 875.30	+
5	1 PC Front wheel rim	R		\$ 1378.10	+
6	1 PC Headlamp	225.00	crn	\$ 981.30	✓
				\$ 5875.50	
Less 10%				\$ 587.55	
				\$ 5287.95	

Labour Charges:-

1	To check wheel alignment	\$ 120.00	60
2	To check wiring	\$ 60.00	20
3	To spray painting	\$ 980.00	500
4	To remove, replace headlamp side mirror & bumper	\$ 900.00	300
Total:		\$ 7347.95	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3042.20
18%
2737.98
3617.98
202
2894.