



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4797H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH / RH @ \$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @ \$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
	LESS 25% DISCOUNT		-463.90	-339.00
			1,391.70	1,017.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERS SENSOR (SN)	NOT WORKING	135.70	135.70
			135.70	135.70
	<u>LABOUR</u>			
	PANEL BEATING.		480.00	280.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	REMOVE / REFIX REVERSE SENSOR.		90.00	30.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
			960.00	510.00
	GRAND TOTAL		2,487.40	1,662.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CC3/QW20008644/T1es3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.