

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008647/R1CF3E2  
**Date:** 26/01/2021

### REFERENCE

|                       |                                               |                      |                    |                                    |
|-----------------------|-----------------------------------------------|----------------------|--------------------|------------------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSNW00051592000 |                                    |
| Claimant Vehicle No : | SLD273R                                       | Insured Vehicle No : | GBG3048H           |                                    |
| Date of Loss:         | 14/08/2020                                    | Nature of Claim:     | TP                 | Claim No: SNM20D202906/C01/TANGHL2 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                                      |             |                   |
|-----------------------------|------------------------------------------------------|-------------|-------------------|
| Reg No:                     | SLD273R                                              |             |                   |
| Make & Model:               | VOLKSWAGEN POLO GP, 1.2 TSI ABS D/AIRBAG 2WD 5DR (A) | Engine No:  | CJZ775542         |
| Reg. Date:                  | 31/05/2016 (Man. Year: 2015)                         | Chassis No: | WVWZZZ6RZGU023948 |
| Colour:                     | White                                                | Odometer:   | 109913 km         |
| Engine Capacity:            | 1197 cc                                              |             |                   |
| Market Value/New Car Price: | N/A                                                  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>                    |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/45 R16    | Rear Tyre Size:  | 215/45 R16    |
| Front Left Side:  | Goodyear 6 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 10,277.28         | 8,140.14          | 2,137.14          | 20.79         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 16,890.00         | 10,630.00         | 6,260.00          | 37.06         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>27,167.28</b>  | <b>18,770.14</b>  | <b>8,397.14</b>   | <b>30.91</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,901.71</b>   | <b>1,313.91</b>   | <b>587.80</b>     | <b>30.91</b>  |
| <b>Nett Amount (S\$)</b>      | <b>29,068.99</b>  | <b>20,084.05</b>  | <b>8,984.94</b>   | <b>30.91</b>  |

### INSPECTION

|                             |            |                                                                                                   |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 03/09/2020 |                                                                                                   |
| Date Inspected:             | 19/08/2020 | Inspected At: Volkswagen Group Singapore Pte Ltd (tuas) (HQ)<br>17 Tuas Ave 9<br>Singapore 639197 |
| Estimated Period of Repair: | 12.0 days  |                                                                                                   |

**Adjuster:** MOHD RASUL

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$2,137.14 NETT)

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Jan 2021)

**Parts:** 144 VOLKSWAGEN POLO GP 1.2 TSI ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLD273R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------------|-----------|-------------|--------------|
| 1   | 1   |          | *FENDER                                      | Bent      | 496.63 FS   | *496.63 FS   |
| 2   | 1   |          | *WHEELHOUSE PROTECTOR LHS FENDER LINER       | Deformed  | 191.44 FS   | *191.44 FS   |
| 3   | 1   |          | *END PLATE FENDER ELEMENT LH                 | Deformed  | 62.20 FS    | *62.20 FS    |
| 4   | 2   |          | *RIVETTED CAP NUT                            | Necessary | 4.46 FS     | *4.46 FS     |
| 5   | 1   |          | *LINING FOR FENDER SATIN B FENDER TOP LINING | Necessary | 11.12 FS    | *11.12 FS    |
| 6   | 1   |          | *SECTIONAL PART-PILLAR A/B                   | Bent      | 1,269.70 FS | *1,269.70 FS |
| 7   | 1   |          | *2K-FULLSCHAUM                               | Necessary | 144.94 FS   | *144.94 FS   |
| 8   | 1   |          | *SEALANT CAB BE SPRAYED                      | Necessary | 61.67 FS    | *61.67 FS    |
| 9   | 1   |          | *ZINC SPRAY                                  | Necessary | 62.88 FS    | *62.88 FS    |
| 10  | 1   |          | *2K-BODY ADHESIVE                            | Necessary | 406.76 FS   | *406.76 FS   |
| 11  | 1   |          | *STICKER WITH PICTOGRAM FO STICKER AIRBAG    | Necessary | 20.78 FS    | *20.78 FS    |
| 12  | 1   |          | *IDENTIFICATION PLATE STICKER (CHASSIS NO)   | Necessary | 355.36 FS   | *355.36 FS   |
| 13  | 1   |          | *TRIM SATIN BLACK A-PILLAR 1/4 TRIM          | * Check   | 20.73 FS    | *- FS        |
| 14  | 3   |          | *RIVET                                       | Necessary | 3.03 FS     | *3.03 FS     |
| 15  | 1   |          | *DOOR LHS FRT DOOR                           | Buckled   | 1,604.45 FS | *1,604.45 FS |
| 16  | 1   |          | *DOOR SEAL OUTER BLACK                       | Necessary | 62.37 FS    | *62.37 FS    |
| 17  | 2   |          | *SOUND ABSORBER LAMINATED DOOR INSULATOR     | Necessary | 82.80 FS    | *82.80 FS    |
| 18  | 1   |          | *DOOR HINGE LOWER                            | * Check   | 102.19 FS   | *- FS        |
| 19  | 1   |          | *BOW SUPPORT DOOR HANDLE                     | * Check   | 100.27 FS   | *- FS        |
| 20  | 1   |          | *DOOR LATCH DOOR LOCK                        | * Check   | 346.94 FS   | *- FS        |
| 21  | 1   |          | *WINDOW REGULATOR WITHOUT                    | * Check   | 354.33 FS   | *- FS        |
| 22  | 1   |          | *WOOFER FRT DOOR SPESKER                     | * Check   | 77.66 FS    | *- FS        |
| 23  | 4   |          | *POP-RIVET                                   | Necessary | 1.92 FS     | *1.92 FS     |
| 24  | 1   |          | *DOOR LHS REAR DOOR                          | Bent      | 1,604.45 FS | *1,604.45 FS |
| 25  | 1   |          | *DOOR SEAL OUTER BLACK                       | Necessary | 85.67 FS    | *85.67 FS    |
| 26  | 1   |          | *DOOR HINGE LHR DOOR LOWER HINGE             | * Check   | 102.19 FS   | *- FS        |
| 27  | 1   |          | *ALLOY WHEEL BLACK-GLOSSY                    | Scratched | 1,360.27 FS | *1,360.27 FS |
| 28  | 1   |          | *RUBBER VALVE                                | Necessary | 2.42 FS     | *2.42 FS     |
| 29  | 1   |          | *WHEEL BEARING HOUSING WIT                   | * Check   | 461.39 FS   | *- FS        |
| 30  | 1   |          | *WHEEL HUB WITH BEARING                      | * Check   | 457.95 FS   | *- FS        |
| 31  | 1   |          | *GUIDE JOINT                                 | * Check   | 113.49 FS   | *- FS        |
| 32  | 1   |          | *TIE ROD                                     | Bent      | 93.90 FS    | *93.90 FS    |
| 33  | 1   |          | *TIE ROD END                                 | Bent      | 103.30 FS   | *103.30 FS   |
| 34  | 2   |          | *RETAINING CLIP                              | Necessary | 9.40 FS     | *9.40 FS     |
| 35  | 1   |          | *DEGREASER CLEANER 500ML                     | Necessary | 38.22 FS    | *38.22 FS    |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** 10,277.28 8,140.14

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                             | Particulars                          | Lab.Type | Repairer's       | Amount           |
|--------------------------------|--------------------------------------|----------|------------------|------------------|
| <b>Labour Items</b>            |                                      |          |                  |                  |
| 1                              | CHECK SHORT CIRCUIT / HARNESS REPAIR | New      | 280.00           | 280.00           |
| 2                              | DIAGNOSTIC AND PROGRAMMING           | New      | 480.00           | 480.00           |
| 3                              | WHEEL ALIGNMENT                      | New      | 360.00           | 360.00           |
| 4                              | R&R RIM & BALANCE                    | New      | 50.00            | 50.00            |
| 5                              | R&R LHS U/CARRIAGE                   | New      | 2,520.00         | 1,260.00         |
| 6                              | LABOUR                               | New      | 6,720.00         | 3,360.00         |
| 7                              | SPRAY PAINT                          | New      | 4,800.00         | 4,000.00         |
| 8                              | TRANSFER DOOR MECHANISM              | New      | 1,680.00         | 840.00           |
| <b>Gross Labour Cost (S\$)</b> |                                      |          | <b>16,890.00</b> | <b>10,630.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >