

Link Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLV122Z

Togolo Harries. 1998CC

JTEKB3GH30J001066

Xiao Chen

Front Number Plate	Missing	30(SN)	✓
Front Number Plate Holder	old	30(SN)	✓
Front Bumper	Detached	811.30	✓
Front Bumper Clips	N/A	50	✓
Front Bumper Side Holder x02	Detached	115.2 x 2 = 230.40	115.10
Front Bumper Sponge	Added	172	✓
Front Bumper Reinforcement	Best	521.70	✓
Front Bumper Sensor x04	2 pieces	481.9 x 4 = 1927.60	362.50
Front Bumper Sensor Holder x04	N/A	25 x 4 = 100	✓
Front Bumper Top Beam	Best	301.10	✓
Front Bumper Undercover	N/A	283.80	X
Front Bumper Undercover Clips	N/A	50	✓
Front Bumper Lower Grille	Added	417.70	✓
Front Bumper Lower Grille Moulding	N/A	185.40	+
Front Bumper Lower Diffuser	Detached	340.20	✓
Front Bumper Side Lamp x02	2 PH	450.5 x 2 = 901	✓
Front Bumper Fog Lamp x02	Smoked	298 x 2 = 596	298
Front Bumper Fog Lamp Mounting x02		35 x 2 = 70	✓

PH smoked

SLV122Z.

Front Grille Assy	cracked	1351.40 ✓
Front Grille Clips	new	20 ✓
Front Grille Bracket	x 02 RH could	$54.2 \times 2 = 108.40$ ✓
Front Support Panel	Distorted	980.40 ✓
Front Support Panel Top Cover	Del	292.90 ✓
Front Support Panel Top Cover Clips	new	30 ✓
Headlamp	x 02 RH Smoked	$6714.5 \times 2 = 13429$ ✓
Headlamp Lower Support Panel	RH Bent	198.50 ✓
Headlamp Lower Support Panel	Sponge RH. could	112.20 ✓
Headlamp ECU	RH } Damaged	1173.40 ✓
Headlamp Ballast	RH. }	1129.10 ✓
Front Fender	x 02 RH Distorted	$1446.3 \times 2 = 2892.60$ ✓
Front RH Fender Inner Panel	RH Bent	855.10 ✓
Front RH Fender Bracket	Bent	45.90 ✓
Front RH Fender Wheel House	Repair	1235.80 ✓
Front RH Fender Inner Shield	Torn	409.10 ✓
Front RH Fender Inner Shield	Clips. new	30 ✓
Bonnet	Distorted	1983.90 ✓
Bonnet Chrome Moulding	cracked	567.50 ✓
Bonnet Chrome Moulding	Clips. new	20 ✓

SLV122Z

Bonnet Lock. Jammed	145.60	✓
Bonnet Hinge x 02 Del	1372 x 2 = 2744.0	✓
Bonnet Damper x 02 Del	299.1 x 2 = 598.20	✓
Bonnet Insulation Trim Sampled	308.50	✓
Bonnet Insulation Trim Clips. n	50	✓
Wiper Panel Garnish. Del	407.40	✓
Wiper Panel Garnish Clips. n	30	✓
Front Windscreen. checked	1976.30	✓
Front Windscreen Moulding	184.90	✓
Front Windscreen Sealant. 1/11	60(SN)	✓
Front Windscreen Solar Film.	300(SN)	259.5
FRP Bracket. n	25(SN)	✓
Wiper Washer Tank. Del	155	✓
Wiper Washer Tank Motor x 4 n	148.40	X
Wiper Washer Tank Neck. x 4 n	30.40	X
Fuse Box. Audited	529.10	✓
Exhaust Manifold Heat Shield. Dented	104.20	✓

SLV 1222.

Air Con Condenser.	NH M	2044.10	+
Air Con Condenser Side Guide	PH D ^{id} x02	108.6 x 2 = 217.20	128.60
Air Con Condenser Side Guide Clips.	M	20	10
Air Con Discharge Pipe.	Best	449.50	✓
Air Con Suction Pipe	NH M	435.80	+
Air Con Liquid Pipe.	Best	345.40	✓
Radiator	NH M	2065	+
Radiator Coolant	M	60(SN)	✓
Front RH Lower Arm.	Best	435.10	✓
Front RH Knuckle Arm.	and	577.40	✓
Front RH Shock Absorber	Best	591.60	✓
Front RH Wheel Hub c/w Bearing	and	306.10	✓
Front RH Drive Shaft.		1367	+
Steering Rack and Pinion	NH	2450.10	+
Steering Cross Member	M	1336	+
Wire Harness		3899	✓

Snapped

SLV122Z

Panel Beating

Spray Painting

Wiring.

To tuff coat

To remove air con condenser }
and to top up air con gas }

To remove radiator and to }
top up coolant }

To remove front windscreen.

To remove dashboard to }
facilitate removal of wire harness }

To remove front undercarriage.

To perform wheel alignment.

Towing Fees

List 2962810

Len 25%: 2222115

S.N: 455

60 ✓

Labour: 3890

total: 2656615

A/S: 21.2K.

14 Days.

~~2000~~ 1600

~~1800~~ 1400

~~200~~ 100

~~200~~ 100

~~150~~ 80

~~150~~ 80

~~180~~ 120

350 * 220.

~~580~~ 250

~~150~~ 100

*