

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLV122Z

Xiao Chen.

Toyota Harrier.

1998CC

JTEKB3GH30J001066

Front Number Plate Missing

30(SN) ✓

Front Number Plate Holder Weld

30(SN) ✓

Front Bumper Distorted

811.30 ✓

Front Bumper Clips New

50 ✓

Front Bumper Side Holder x02 Distorted

115.2 x 2 = 230.40 ✓

Front Bumper Sponge Crushed

172 ✓

Front Bumper Reinforcement Best

521.70 ✓

Front Bumper Sensor x04 2 pieces

481.9 x 4 = 1927.60 ✓

Front Bumper Sensor Holder x04 New

25 x 4 = 100 ✓

Front Bumper Top Beam Best

301.10 ✓

Front Bumper Undercover New

283.80 X ✓

Front Bumper Undercover clips New

50 ✓

Front Bumper Lower Grille Crushed

417.70 ✓

Front Bumper Lower Grille Mounting New

185.40 + ✓

Front Bumper Lower Diffuser Deformed

340.20 ✓

Front Bumper Side Lamp x02 2 PH

450.5 x 2 = 901 ✓

Front Bumper Fog Lamp x02 Smashed

298 x 2 = 596.298 ✓

Front Bumper Fog Lamp Mounting x02

35 x 2 = 70 ✓

RH Smashed

SLV102Z.

Front Grille Assy	crushed	1351.40 ✓
Front Grille Clips	new	20 ✓
Front Grille Bracket	x 02 RH and	54.2 x 2 = 108.40 ✓
Front Support Panel	Distorted	980.40 ✓
Front Support Panel Top Cover	Del	292.90 ✓
Front Support Panel Top Cover Clips	new	30 ✓
Headlamp	x 02 RH Smashed	6714.5 x 2 = 13429. ✓
Headlamp Lower Support Panel	RH Bent	198.50 ✓
Headlamp Lower Support Panel Sponge	RH. crushed	112.20 ✓
Headlamp ECU	RH	1173.40 ✓
Headlamp Ballast	RH. } Damaged	1129.10 ✓
Front Fender	x 02 RH Distorted	1446.3 x 2 = 2892.60 ✓
Front RH Fender Inner Panel	RH Bent	855.10 ✓
Front RH Fender Bracket	Bent	45.90 ✓
Front RH Fender Wheel House	Repair	1235.80. ✓
Front RH Fender Inner Shield	Torn	409.10 ✓
Front RH Fender Inner Shield Clips	new	30 ✓
Bonnet	Distorted	1983.90 ✓
Bonnet Chrome Moulding	crushed	567.50 ✓
Bonnet Chrome Moulding Clips	new	20 ✓

SLV1222

Bonnet Lock . Jammed	145.60 ✓
Bonnet Hinge x 02 Bent	$137.2 \times 2 = 274.40$ ✓
Bonnet Damper x 02 De-rod	$299.1 \times 2 = 598.20$ ✓
Bonnet Insulation Trim angled	308.50 ✓
Bonnet Insulation Trim Clips. n	50 ✓
Wiper Panel Garnish. De-rod	407.40 ✓
Wiper Panel Garnish Clips. n	30 ✓
Front Windscreen. checked	1976.30. ✓
Front Windscreen Moulding } Front Windscreen Sealant. } Front Windscreen Solar Film. }	184.80 ✓ New 60(SW) ✓ 300(SW) 257/20 ✓
FRP Bracket. n	25(SW) ✓
Wiper Washer Tank. De-rod	155 ✓
Wiper Washer Tank Motor x n	148.40 X
Wiper Washer Tank Nock. n	32.40 X
Fuse Box. Angled	529.10 ✓
Exhaust Manifold Heat Shield. Dented	104.20 ✓

SLV122Z.

Air Con Condenser.	NH M	2044.10	X
Air Con Condenser Side Guide	RH Dmg x02	1086x2 = 2172.0	10860
Air Con Condenser Side Guide Clips.	M	20	10
Air Con Discharge Pipe.	Bert	449.50	✓
Air Con Suction Pipe	NH M	435.80	X
Air Con Liquid Pipe.	Bert	345.40	✓
Radiator	NH M	2065	X
Radiator Coolant	M	60(SN)	✓
Front RH Lower Arm.	Bert	435.10	✓
Front RH Knuckle Arm.	Dmg	577.40	✓
Front RH Shock Absorber	Bert	591.60	✓
Front RH Wheel Hub c/w Bearing	Dmg	306.10	✓
Front RH Drive Shaft.		1367	X
Steering Rack and Pinion	NH	2450.10	X
Steering Cross Member	M	1336	X

SLV122Z

Panel Beating	2000 1600
Spray Painting	1800 1400
Wiring.	200 100
To tuff coat	200 100
To remove air con condenser and to top up air con gas }	150 80
To remove radiator and to top up coolant }	150 80
To remove front windscreen.	180 120
To remove dashboard to facilitate removal of wire harness }	350 x
To remove front undercarriage.	580 250
To perform wheel alignment.	150 100
Towing Fees	60 ✓
list: 29628.0	Labour: 3890
len 25%: 22221.15	total: 26566.15
S.N: 455	H/s: 21.2K.
	14 Days.