

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20008652/KTF3E2
Date: 28/09/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000134
Claimant Vehicle No : SHD401K	Insured Vehicle No :	SLF2764S
Date of Loss: 14/08/2020	Nature of Claim:	TP Claim No: M2003986

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD401K	Engine No:	M9R8839C003391
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283412
Reg. Date:	17/10/2016 (Man. Year: 2016)	Odometer:	643031 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,451.19	13,121.35	27,329.84	67.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,170.00	4,200.00	6,970.00	62.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,621.19	17,321.35	34,299.84	66.45
Approved Total (Overridden) (S\$)		13,850.00		
(S\$)	51,621.19	13,850.00	37,771.19	73.17
+ GST 7.00/7.00% (S\$)	3,613.48	969.50	2,643.98	73.17
Nett Amount (S\$)	55,234.67	14,819.50	40,415.17	73.17

INSPECTION

Date of Assignment:	19/08/2020	
Date Inspected:	18/08/2020 Inspected At:	Trans-Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	14.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Sep 2020)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD401K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Distorted / Cracked	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	-	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Buckled	82.10 FL	-	*82.10 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	-	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	-	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	-	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	-	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	-	*114.50 FL
13	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	-	*- FL
14	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	-	*- FL
15	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
16	1		*OUTER PANEL REAR (END PANEL) TRIM	Mtg Cracked	404.56 FL	-	*404.56 FL
17	1		*TAILLAMP RH	Mtg Cracked	401.40 FL	-	*401.40 FL
18	1		*TAILLAMP PANEL RH	Bent	401.40 FL	-	*401.40 FL
19	1		*TAILLAMP LH	Mtg Cracked	401.40 FL	-	*401.40 FL
20	1		*TAILLAMP PANEL LH	Repair	401.40 FL	-	*- FL
21	1		*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
22	1		*BOOT FINISHER	Serviceable	344.70 FL	-	*- FL
23	1		*BOOT WEATHERSTRIP (\$178.20) (50%)	Distorted / Dented	160.38 FS	-	*89.10 FS
24	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	-	*- FL
25	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	-	*277.70 FL
26	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
27	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
28	1		*BOOT STRUT LH	Serviceable	145.10 FL	-	*- FL
29	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	-	*- FL
30	1		*BOOT STRUT RH	Serviceable	145.10 FL	-	*- FL
31	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
32	1		*BOOT HINGE RH	Repair	254.20 FL	-	*- FL
33	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
34	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	-	*- FL
35	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	-	*- FL
36	1		*BOOT SWITCH	Serviceable	113.00 FL	-	*- FL
37	1		*EXHAUST REAR	Bent	4,737.24 FS	-	*3,200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
38	1		*EXHAUST CAP REAR	Dented	125.40 FL	-	*125.40 FL
39	1		*REAR RH FENDER PANEL	Buckled	1,933.20 FL	-	*1,933.20 FL
40	1		*WHEELARCH REAR RH	Distorted	275.40 FL	-	*275.40 FL
41	1		*FENDER PANEL INNER TRIM REAR RH	Repair	671.45 FL	-	*- FL
42	1		*SPARE WHEEL PANEL	Bent / Buckled	1,229.40 FL	-	*1,229.40 FL
43	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	-	*- FL
44	1		*SPARE WHEEL PANEL BRACKET RH	Repair	69.20 FL	-	*- FL
45	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*- FL
46	1		*CHASSIS PANEL REAR RH	Repair	2,192.40 FL	-	*- FL
47	1		*FENDER PANEL INNER REAR RH	Repair	1,241.60 FL	-	*- FL
48	1		*FENDER INNER BOARD RH	Serviceable	561.40 FL	-	*- FL
49	1		*WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	-	*- FL
50	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	-	*- FL
51	1		*DOOR LOCK REAR RH	Repair	467.30 FL	-	*- FL
52	1		*KNUCKLE ARM REAR RH	Serviceable	472.10 FL	-	*- FL
53	1		*WHEEL HUB NUT	Serviceable	41.80 FL	-	*- FL
54	1		*WHEEL HUB CAP	Serviceable	30.50 FL	-	*- FL
55	1		*ABS SENSOR REAR RH	Serviceable	190.50 FL	-	*- FL
56	1		*REAR AXLE	Serviceable	3,469.00 FL	-	*- FL
57	1		*AXLE SPRING ARM RH	Serviceable	220.60 FL	-	*- FL
58	1		*UPPER CONRTOL ARM REAR RH	Serviceable	543.50 FL	-	*- FL
59	1		*ABSORBER REAR	Serviceable	217.30 FL	-	*- FL
60	1		*ABSORBER MOUNTING REAR	Serviceable	49.40 FL	-	*- FL
61	1		*STABILIZER BAR REAR	Serviceable	427.90 FL	-	*- FL
62	1		*STABILIZER LINK REAR	Serviceable	55.20 FL	-	*- FL
63	1		*SUBFRAME ARM REAR RH	Serviceable	198.33 FL	-	*- FL
64	1		*RODE-LONG REAR RH	Serviceable	120.16 FL	-	*- FL
65	1		*KNUCKLE HUB+BEARING RH	Serviceable	272.30 FL	-	*- FL
66	1		*EXTENSION-REAR RH SIDE MEMBER	Serviceable	233.20 FL	-	*- FL
67	1		*SET PARKING AID	Shorted	700.00 FS	-	*400.00 FS
68	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	-	*75.00 FS
69	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	65.00 FS	-	*- FS
70	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	60.00 FS	-	*- FS
71	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	50.00 FS	-	*- FS
72	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	60.00 FS	-	*- FS
73	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	50.00 FS	-	*- FS
74	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	70.00 FS	-	*- FS
75	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	-	*75.00 FS
76	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
77	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
78	1		*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	-	*- FS
79	1		*TAILLAMP CLIP LH	Necessary	40.00 FS	-	*5.00 FS
80	1		*TAILLAMP CLIP RH	Necessary	40.00 FS	-	*5.00 FS
81	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	-	*30.00 FS
82	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	-	*- FS
83	1		*EXHAUST MOUNTING	Serviceable	90.00 FS	-	*- FS
84	1		*FENDER INNER TRIM CLIP RH	Necessary	60.00 FS	-	*60.00 FS
85	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	65.00 FS	-	*- FS
86	2		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	-	*40.00 FS
87	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
88	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	-	*30.00 FS
89	2		*SEAM SEALANT	Not Necessary	190.00 FS	-	* - FS
90	1		*REAR RENAULT TYRE 215/60/16	Serviceable	330.00 FS	-	* - FS
91	1		*REAR RENAULT TYRE RIM	Serviceable	380.00 FS	-	* - FS
92	1		*SPARE TYRE	Serviceable	330.00 FS	-	* - FS
93	1		*SET END PANEL TRIM CLIP	Not Necessary	55.00 FS	-	* - FS
94	1		*SPARE TYRE 215/60/16	Serviceable	330.00 FS	-	* - FS
95	1		*SPARE TYRE RIM	Serviceable	380.00 FS	-	* - FS
96	1		*EXHAUST BRACKET	Repair	60.00 FS	-	* - FS
97	1		*EXHAUST SCREW	Serviceable	50.00 FS	-	* - FS
98	1		*REAR DOOR STICKER 6555-3333	Not Necessary	100.00 FS	-	* - FS
99	1		*BOOT TRIM BOARD CLIP	Not Necessary	65.00 FS	-	* - FS
100	1		*EXHAUST CLAMP	Serviceable	68.80 FS	-	* - FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	43,862.28	14,127.16
- List Item Discount on L Items 10.00/10.00% (\$)	3,411.09	1,005.81
Total Parts (\$)	40,451.19	13,121.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
2	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN REAR AND CENTRE EXHAUST PIPE	New	380.00	80.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	120.00
4	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TOWING FEES	New	150.00	50.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,800.00	2,000.00
8	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	250.00
11	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
12	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
13	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	120.00
14	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
15	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,800.00	1,100.00
17	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	220.00
18	TO DISMANTLE AND REFIT REAR AXLE ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
19	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
20	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
21	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
22	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING	New	380.00	0.00
23	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
Gross Labour Cost (\$\$)			11,170.00	4,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >