

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM120008653/KVF3E2

Date: 02/09/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MR003940

Claimant Vehicle No : SHB7658B

Insured Vehicle No : SLF1661L

Date of Loss: 15/08/2020

Nature of Claim: TP

Claim No: M2003988

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7658B

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2C10276

Reg. Date: 24/05/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU803080094

Colour: Metallic Pearl White/Red

Odometer: 85882 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side: Goodyear 3 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Goodyear 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,194.02	978.50	6,215.52	86.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	485.00	4,385.00	90.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,064.02</b>	<b>1,463.50</b>	<b>10,600.52</b>	<b>87.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>844.48</b>	<b>102.45</b>	<b>742.03</b>	<b>87.87</b>
<b>Nett Amount (S\$)</b>	<b>12,908.50</b>	<b>1,565.95</b>	<b>11,342.55</b>	<b>87.87</b>

### INSPECTION

Date of Assignment: 19/08/2020

Date Inspected: 18/08/2020 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk  
(HQ)  
No 2 Ang Mo Kio St 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB7658B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Buckled	442.60 FL	-	*442.60 FL
2	1		*REAR BUMPER TOWING COVER	Missing	15.40 FL	-	*15.40 FL
3	1		*GUARD, REAR BUMPER, CENTER	Bent	576.30 FL	-	*576.30 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	332.70 FL	-	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	-	*- FL
6	1		*ANTENNA, ELECTRICAL KEY	Serviceable	72.00 FL	-	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	-	*- FL
8	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	-	*- FL
9	1		*PANEL SUB-ASSY, BODY LOWER BACK	Repair	650.30 FL	-	*- FL
10	1		*REAR BUMPER SIDE RH	Mtg Cracked	123.70 FL	-	*123.70 FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	-	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	-	*- FL
13	1		*COVER, DECK TRIM, REAR	Serviceable	126.70 FL	-	*- FL
14	1		*COVER, FLOOR UNDER, NO.1	Serviceable	175.10 FL	-	*- FL
15	1		*COVER, REAR FLOOR	Serviceable	229.90 FL	-	*- FL
16	1		*PANEL SUB-ASSY, QUARTER, RH	Repair	871.50 FL	-	*- FL
17	1		*REAR FENDER LINER	Serviceable	139.80 FL	-	*- FL
18	1		*SEAL, REAR BUMPER SIDE, RH	Serviceable	88.50 FL	-	*- FL
19	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	-	*80.00 FS
21	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.90 FS	-	*- FS
22	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	54.60 FS	-	*- FS
23	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	54.60 FS	-	*- FS
24	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	-	*- FS
25	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	-	*- FS
26	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	-	*30.00 FS
27	1		*REAR WHEEL COVER	Serviceable	211.50 FS	-	*- FS
28	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	70.00 FS	-	*- FS
29	1		*SET TAILLAMP LOWER CLIP	Not Necessary	40.00 FS	-	*- FS
30	1		*SET TAILLAMP UPPER CLIP	Not Necessary	40.00 FS	-	*- FS
31	2		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*- FS
32	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
33	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	120.00 FS	-	*- FS
34	1		*SET REAR FENDER LINER CLIP	Not Necessary	70.00 FS	-	*- FS
35	1		*SET END PANEL TRIM CLIP	Not Necessary	55.00 FS	-	*- FS
36	2		*SEAM SEALANT	Not Necessary	170.00 FS	-	*- FS
37	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	130.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 8,747.50 1,268.00

**- List Item Discount on L Items 25.00/25.00% (\$\$)** 1,553.48 289.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
Total Parts (S\$)					7,194.02		978.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
2	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
4	PUTTY AND SPRA YPAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
8	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
11	TO TRANSFER OF END PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,870.00</b>	<b>485.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >