

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20008655/R1CF3Q2**Date:** 18/03/2021**REFERENCE**

Insured/Claimant: CHAN RUO JUN Policy No: 1900130169  
Date of Loss: 05/06/2020 Nature of Claim: OD Claim No: 2754011144SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLR4875D**  
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZ508633  
Reg. Date: 16/08/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V4J1005325  
Colour: Black Odometer: 56362 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$85,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,822.00	4,850.40	5,971.60	55.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,542.00	2,740.00	51.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,104.00</b>	<b>7,392.40</b>	<b>8,711.60</b>	<b>54.10</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,127.28</b>	<b>517.47</b>	<b>609.81</b>	<b>54.10</b>
<b>Nett Amount (S\$)</b>	<b>17,231.28</b>	<b>7,909.87</b>	<b>9,321.41</b>	<b>54.10</b>

**INSPECTION**

Date of Assignment: 19/08/2020

Date Inspected: 19/08/2020 Inspected At:

281 Alexandra Road  
Repairer: Premium Automobiles Pte  
Ltd  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,894.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	36.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	505.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	280.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM-LH	Not Necessary	153.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ADAPTER-LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	177.00 FS	*- FS
9	1		*FRONT FENDER-LH	Bent	802.00 FS	*641.60 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS
11	1		*FRONT FENDER BRACKET-LH	Not Necessary	36.00 FS	*- FS
12	1		*FRONT FENDER BRACE	Not Necessary	90.00 FS	*- FS
13	1		*WHEEL HOUSING LINER SEAL-LH	Not Necessary	32.00 FS	*- FS
14	1		*WHEEL HOUSING LINER-LH	Not Necessary	160.00 FS	*- FS
15	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
16	1		*LED HEADLIGHT-LH	Scratched	5,193.00 FS	*4,154.40 FS
17	1		*LIFT CYLINDER	Not Necessary	134.00 FS	*- FS
18	1		*FRONT ALUMINIUM RIM-LH	Not Necessary	666.00 FS	*- FS
19	1		*SUNDRIES	Necessary	300.00 FS	*54.40 FS
					<b>Total Parts (\$\$)</b>	<b>10,822.00 4,850.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,282.00</b>	<b>2,542.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >