

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008656/R1CF3E2

Date: 05/03/2021

REFERENCE

Insured/Claimant:	UDAI SINGH	Policy No:	1800001279	Claim No:	9289032361SG
Date of Loss:	09/08/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX5405B	Engine No:	CJE102930
Make & Model:	AUDI A5, 1.8 SPORTSBACK TFSI MU (A)	Chassis No:	WAUZZZ8T2FA059034
Reg. Date:	17/12/2015 (Man. Year: 2015)	Odometer:	80954 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	253/35Z R19	Rear Tyre Size:	253/35Z R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,278.00	12,558.72	8,719.28	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,572.00	9,542.00	6,030.00	38.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	36,850.00	22,100.72	14,749.28	40.03
+ GST 7.00/7.00% (S\$)	2,579.50	1,547.05	1,032.45	40.03
Nett Amount (S\$)	39,429.50	23,647.77	15,781.73	40.03

INSPECTION

Date of Assignment:	19/08/2020		
Date Inspected:	19/08/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,569.00 FS	*2,055.20 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	225.00 FS	*- FS
3	1	*REAR BUMPER CARRIER	Bent	636.00 FS	*508.40 FS
4	2	*REAR BUMPER BRACKET HOLDER - LH / RH	Bent	440.00 FS	*352.00 FS
5	1	*REAR BUMPER SPOILER	Scratched	273.00 FS	*218.00 FS
6	2	*REAR BUMPER GUIDE SECTION - LH / RH UPPER	Serviceable	38.00 FS	*- FS
7	1	*REAR PARKING AID SENSOR - INNER / OUTER (3 Pcs)	Missing (1Pc only)	600.00 FS	*200.00 FS
8	1	*SET REAR BUMPER WIRING	Serviceable	510.00 FS	*- FS
9	1	*REAR LID	Bent	2,608.00 FS	*2,086.40 FS
10	1	*REAR LID ATTACHMENT PARTS	Serviceable	113.00 FS	*- FS
11	2	*REAR LID HINGE - LH / RH	Bent	452.00 FS	*361.60 FS
12	1	*REAR LID FLAP GASKET	Necessary	222.00 FS	*177.60 FS
13	1	*REAR LID FLAP GASKET - UPPER REAR	Serviceable	100.00 FS	*- FS
14	1	*REAR LID STRIKER PLATE	Serviceable	122.00 FS	*- FS
15	1	*REAR LID LOCK	Bent	169.00 FS	*135.20 FS
16	1	*LID LOCK PUSH BUTTON	Deformed	172.00 FS	*137.60 FS
17	1	*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
18	2	*GAS FILLED STRUT	Serviceable	235.00 FS	*- FS
19	1	*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
20	1	*AS INSCRIPTION	Necessary	95.00 FS	*75.36 FS
21	1	*TFSI INSCRIPTION	Necessary	95.00 FS	*75.36 FS
22	1	*REAR WINDSCREEN	Necessary	1,108.00 FS	*886.40 FS
23	1	*PRIMER	Necessary	19.00 FS	*14.96 FS
24	1	*LED TAILLIGHT - LH / RH	NsCut/Scratched/OsServiceable	2,450.00 FS	*980.00 FS
25	1	*LED TAILLIGHT - LH / RH	Ns Scratched / Os Serviceable	1,716.00 FS	*686.00 FS
26	1	*LED LICENSE PLATE LIGHT	Cracked (1Pc Only)	113.00 FS	*45.12 FS
27	1	*ADDITIONAL BRAKE LIGHT	Necessary	446.00 FS	*356.40 FS
28	1	*REAR CROSS PANEL - OUTER	Bent	519.00 FS	*415.20 FS
29	1	*CROSS PANEL - LOWER	Bent	859.00 FS	*687.20 FS
30	1	*CROSS PANEL REINFORCEMENT - INNER	Bent	668.00 FS	*534.40 FS
31	1	*REAR CROSS PANEL TRIM	Cracked	175.00 FS	*140.00 FS
32	1	*LUGGAGE COMPARTMENT FLOOR	Serviceable	701.00 FS	*- FS
33	1	*REAR LID TRIM PANEL	Scratched	478.00 FS	*382.00 FS
34	1	*REAR SILENCER - LH	Serviceable	824.00 FS	*- FS
35	1	*REAR SILENCER DUAL CLIP	Not Necessary	57.00 FS	*- FS
36	1	*REAR SILENCER BRACKET	Serviceable	57.00 FS	*- FS
37	1	*REAR NO PLATE	Bent	60.00 FS	*60.00 FS
38	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
39	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
40	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
41	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
42	1	*SUNDRIES	Necessary	400.00 FS	*86.08 FS
43	1	*REAR LID GUARD PLATE	Deformed	61.00 F	*48.72 F
44	1	*REAR LID COVER FOR LOCK	Deformed	8.00 F	*6.00 F
45	1	*CABLE HOLDER FOR REAR LID TRIM PANEL	Deformed	45.00 F	*35.52 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,278.00 12,558.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL	New	480.00	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND REWELD REAR END PANELLING OUTER AND INNER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	4,500.00	2,200.00
8	TO RENEW LHS REAR EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	0.00
9	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN	New	200.00	200.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO REPAIR RHS TAIL LAMP PANEL AND LHS TAIL LAMP PANEL	New	1,200.00	1,000.00
12	TO RESPRAY RHS TAIL LAMP PANEL, LHS TAIL LAMP PANEL AND RH SIDE FENDER	New	2,000.00	1,650.00
13	TO DISLODGE AND REINSTALL ROOF LINER TO FACILITATE THE RENEWAL OF REAR LID HINGES	New	280.00	280.00
Gross Labour Cost (\$\$)			15,572.00	9,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >