

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 19 Aug 2020

Preliminary Advice

Vehicle No	: SKA5661Z	Accident Date	: 13/08/2020
Make	: TOYOTA WISH	Policy No.	: 2100251033
Assignment Date	: 19/08/2020	Excess	: S\$1,000.00
Date of Inspection	: 19/08/2020	Est. Duration of Repair	: 14
Inspection At	: S THREE AUTOMOTIVE RECOVERY PTE LTD (HQ) BLK 8 SIN MING INDUSTRIAL ESTATE, #01-64/66 SECTOR C SINGAPORE 575643		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,905.25
Revised Amount	:S\$	18,793.93
Check Items (Estimated)	:S\$	7,352.45
Total	:S\$	26,146.38

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,000.00
COE / PARF Rebate	:S\$	13,750.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,250.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.