



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9780G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	MOULDING ASSY, BODY ROCKER PANEL, LH	SERVICEABLE	594.80	-
1	PANEL SUB-ASSY, REAR DOOR, LH	BENT	1,294.90	1,294.90
1	TAPE, BLACK OUT, NO.1 REAR LH	NECESSARY	21.90	21.90
1	TAPE, BLACK OUT, NO.2 REAR LH	NECESSARY	34.90	34.90
1	TAPE, BLACK OUT, NO.3 REAR LH	NECESSARY	15.40	15.40
1	PANEL SUB-ASSY, FRONT DOOR, LH	BENT	1,300.70	1,300.70
1	TAPE, BLACK OUT, NO.1 FRT LH	NECESSARY	13.30	13.30
1	TAPE, BLACK OUT, NO.2 FRT LH	NECESSARY	43.50	43.50
1	TAPE, BLACK OUT, NO.3 FRT LH	NECESSARY	26.30	26.30
1	HINGE ASSY, REAR DOOR, LOWER LH	TO REPAIR SEE LABOUR	87.10	-
	LESS 25% DISCOUNT		-858.20	-687.72
			2,574.60	2,063.18
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	100.00	60.00
1	SET ROCKER PANEL MOULDING CLIP (SN)	NOT NECESSARY	65.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	100.00	60.00
			265.00	120.00
<u>LABOUR</u>				
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HINGE ASSY, REAR DOOR, LOWER LH.		1,200.00	400.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	440.00
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00

Report Ref No. CS/TP20008659/Ktf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHERS, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
			3,540.00	1,040.00
GRAND TOTAL			6,379.60	3,223.18
RECOMMENDED COST OF REPAIRS				3,223.18

Report Ref No. CS/TP20008659/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.