

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8229M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	I40VC PANEL-FENDER RH	TO REPAIR SEE LABOUR	663.00	-
1	I40VC LAMP ASSY-HEAD RH (CRACKED)	OLD DAMAGED	1,388.00	-
	LESS 20% DISCOUNT		-410.20	-
			1,640.80	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF I40VC PANEL-FENDER RH.		300.00	280.00
	SPRAYPAINT CHARGE.		300.00	200.00
	CHECK ALL LIGHTING.		50.00	30.00
			650.00	510.00
	GRAND TOTAL		2,290.80	510.00

Report Ref No. NS/INC20008664/T1vf3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.