

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20008666/GCF3N2**Date:** 21/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00054202004

**Claimant Vehicle No :** SKJ5713K **Insured Vehicle No :** SKS93B

Date of Loss: 07/08/2020 Nature of Claim: TP Claim No: SNM20D202853/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ5713K**

Make & Model: BMW 316I, 1.6 (A) Engine No: A120J433N13B16A

Reg. Date: 19/04/2013 (Man. Year: 2013) Chassis No: WBA3A12090J720126

Colour: Black Odometer: 146306 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 265/30R19 Rear Tyre Size: 265/30R19

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,370.06	3,546.09	8,823.97	71.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	970.00	1,830.00	65.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,170.06</b>	<b>4,516.09</b>	<b>10,653.97</b>	<b>70.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	15,170.06	3,600.00	11,570.06	76.27
<b>+ GST 7.00/7.00% (S\$)</b>	1,061.90	252.00	809.90	76.27
<b>Nett Amount (S\$)</b>	<b>16,231.96</b>	<b>3,852.00</b>	<b>12,379.96</b>	<b>76.27</b>

INSPECTION

Date of Assignment: 19/08/2020

Date Inspected: 20/08/2020 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
<b>Parts:</b> 143	BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKJ5713K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,987.40 FL	*1,037.05 FL
2	1		*FRONT BUMPER RETAINER (LHS)	Not Necessary	89.70 FL	*- FL
3	1		*FRONT BUMPER RETAINER (RHS)	Not Necessary	89.70 FL	*- FL
4	1		*FRONT BUMPER BRACKET (LHS)	Not Necessary	94.60 FL	*- FL
5	1		*FRONT BUMPER BRACKET (RHS)	Not Necessary	94.60 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	874.60 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	265.40 FL	*- FL
8	1		*FRONT BUMPER FOG LIGHT	Not Necessary	412.50 FL	*- FL
9	1		*FRONT BUMPER FOG LIGHT COVER	Not Necessary	167.80 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	369.70 FL	*- FL
11	1		*FRONT BUMPER RADIATOR GRILLE (LHS)	Not Necessary	256.40 FL	*- FL
12	1		*FRONT BUMPER RADIATOR GRILLE (RHS)	Not Necessary	256.40 FL	*- FL
13	1		*FRONT BUMPER LOWER LIP	Not Necessary	789.40 FL	*- FL
14	1		*HEADLAMP (LHS)	Broken	1,880.40 FL	*1,880.40 FL
15	1		*HEADLAMP NOZZLE (LHS)	Not Necessary	154.10 FL	*- FL
16	1		*FRONT FENDER (LHS)	Broken off	1,154.60 FL	*762.65 FL
17	1		*FRONT FENDER SHIELD (LHS)	Not Necessary	315.40 FL	*- FL
18	1		*LHS FRONT ABSORBER (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*LHS FRONT LOWER ARM (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*LHS FRONT UPPER ARM (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*LHS FRONT KNUCKLE (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*LHS FRONT KNUCKLE HUB (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*LHS FRONT WHEEL BEARING (NPA)	Not Necessary	0.00 FL	*- FL
24	10		*FRONT BUMPER CLIP	Necessary	90.00 FS	*30.00 FS
25	10		*LHS FRONT FENDER SHIELD CLIP	Necessary	90.00 FS	*20.00 FS
26	1		*LHS FRONT RIM	Repair	2,500.00 FS	*- FS
27	1		*LHS FRONT TYRE	Not Necessary	900.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,832.70</b>	<b>3,730.10</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	462.64	184.01
<b>Total Parts (\$\$)</b>	<b>12,370.06</b>	<b>3,546.09</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS,INCLUSIVE OF REPLACEMENT PARTS	New	1,200.00	400.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,000.00	500.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS }	New	50.00	40.00
4	TO SUPPLY UNDERCOATING/PUTTY ON PARTS REPLACED }	New	50.00	0.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	0.00
6	TO CONDUCT HEADLAMP FOCUS }	New	100.00	30.00
7	TO CHECK WIRING AND LIGHTING SYSTEM }	New	50.00	0.00
8	CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	150.00	0.00
9	RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>2,800.00</b>
				<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >