




Service Request Details

Claim
SOM02SCU

Reference
None 

Loss Date
August 14, 2020

Report Date
Aug 18, 2020 9:51:41 AM

Request Date
August 19, 2020

Due Date
August 19, 2021

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss
Own Damage

Services
Investigation

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
SGC4334L

Model

COROLLA ALTIS 1.6

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

RAJAGOPAL SETHU S/O

BLK 104A ANG MO KIO ST 11, #02-73, 560104, Singapore

LUNGI@HOTMAIL.COM

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

pls conduct investigation and obtain statement from insured - the center portion of the tyre barely meet the requirement. However, the outer portion of the tyre had worn out badly and we are able to see the inner gauze protruding. As the front tyres are worn out, road grip and water channeling are reduced, hydroplaning will occurs and vehicle could skid while turning during rainy day/wet road condition. nsured reported car skidded due to wet road. Front LH tyre worn off condition could possibly caused lack of grip on road and skid

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)