

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20008675/QRS3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993880

**Claimant**  
**Vehicle No :** SHB1097J **Insured Vehicle No :** GBH4630P

Date of Loss: 14/08/2020 Nature of Claim: TP Claim No: 6597372077SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB1097J</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR2F35397
Reg. Date:	17/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU303089267
Colour:	Maroon	Odometer:	41137 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,531.50	1,852.89	4,678.61	71.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,235.00	1,000.00	1,235.00	55.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>8,766.50</b>	<b>2,852.89</b>	<b>5,913.61</b>	<b>67.46</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Car Rental (5.0 x S\$114.49/day) (S\$)</b>		572.45		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>3,682.34</b>		

### INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 17/08/2020 Inspected At: SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 4.0 days

**Adjuster:** OI SUN PIN

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Crumpled	485.60 F	*364.20 F
2	1		*PAD ,RR BUMPER ,RH & LH,3 (DISC 25%) (2 PCS)	Necessary	11.00 F	*8.25 F
3	2		*PAD ,RR BUMPER ,RH & LH,2 (DISC 25%)	Necessary	4.00 F	*3.00 F
4	2		*PAD ,RR BUMPER ,RH & LH,1 (DISC 25%)	Necessary	4.00 F	*3.00 F
5	2		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%)	Necessary	11.30 F	*8.48 F
6	1		*RETAINER ,RR BUMPER ,RH (DISC 25%)	Broken	132.60 F	*99.45 F
7	1		*RETAINER ,RR BUMPER ,LH (DISC 25%)	Broken	132.60 F	*99.45 F
8	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	4.50 F	*33.75 F
9	1		*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Crumpled	374.50 F	*280.88 F
10	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	47.90 F	*35.93 F
11	1		*NAME PLATE (HYBRID) LUGGAGE (DISC 25%)	Necessary	54.60 F	*40.95 F
12	1		*NAME PLATE (PRIUS) LUGGAGE (DISC 25%)	Necessary	54.60 F	*40.95 F
13	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB (DISC 25%)	Cracked	913.60 F	*685.20 F
14	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
15	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
16	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
17	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
18	2		*STOPPER ,RR BUMPER ,RH & LH	Serviceable	4.50 F	*- F
19	1		*SEAL ,RR BUMPER ,RH	Serviceable	118.30 F	*- F
20	1		*SEAL ,RR BUMPER ,LH	Serviceable	118.30 F	*- F
21	1		*REAR BUMPER REFLECTOR ASSY	Serviceable	39.00 F	*- F
22	1		*REAR BUMPER REFLECTOR ASSY	Serviceable	39.00 F	*- F
23	1		*COVER ,REAR FLOOR UNDER ,RH	Serviceable	175.10 F	*- F
24	1		*COVER ,REAR FLOOR UNDER ,LH	Serviceable	241.90 F	*- F
25	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
26	1		*LENS & BODY ,REAR COMBINATION LAMP,LH	Serviceable	339.60 F	*- F
27	1		*COVER ,REAR COMBINATION LAMP ,LH	Serviceable	69.90 F	*- F
28	1		*SOCKET & WIRE SUB-ASSY ,REAR	Serviceable	52.30 F	*- F
29	1		*LENS & BODY ,REAR COMBINATION LAMP	Serviceable	261.00 F	*- F
30	1		*EMBLEM ,SIDE PANEL (HYBRID)	Serviceable	54.60 F	*- F
31	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	651.00 F	*- F
32	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
33	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
34	1		*LAMP ASSY ,REAR ,LH	Serviceable	293.60 F	*- F
35	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Repair	913.60 F	*- F

F=Franchise part.

**Total Parts (\$\$) 6,531.50 1,852.89**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	707.00	450.00
2	SPRAY PAINT	New	1,168.00	500.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,235.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >