



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200917

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 18/02/2022
Reference CC4/FCI20008678/Kes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. CB 6873L
Insured Veh. SHC 7284R
Claim No. D20003279MFSH/1
Policy No. D-20094921MFSH
Accident Date 13/08/2020
Inspection Date 07/09/2020

Description	Total
Survey Inspection	277.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	277.00
GST (7%)	19.39
Grand Total	296.39

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20008678/Kes3q2	
			Date: 18/02/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7284R	Veh. Inspected	CB 6873L	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003279MFSH/1	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	19/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN (M)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	JN1HG4E25Z0701424	Colour	SILVER	
Odometer	802655 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	5 mm	
L/H Front Tyre	195 R15X8	MICHELIN	5 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	3 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/08/2020	Inspection Date	07/09/2020	
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 6873L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	572.80	572.80
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER FOG LAMP GARNISH ,LH	DENTED	85.00	85.00
1	FRONT BUMPER SIDE RETAINER -LH	DISTORTED	137.20	137.20
1	FRONT BUMPER SIDE RETAINER -RH	SERVICEABLE	137.20	-
1	FRONT CORNER FENDER -LH	TO REPAIR SEE LABOUR	223.90	-
1	FRONT DOOR OUTER MOULDING -LH	SERVICEABLE	152.90	-
1	FRONT DOOR -LH	TO REPAIR SEE LABOUR	1,668.50	-
1	FRONT DOOR WEATHERSTRIP -LH	SERVICEABLE	125.60	-
1	FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	82.50	-
1	FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	82.50	-
1	FRONT DOOR INNER TRIM -LH	SERVICEABLE	420.00	-
1	FRONT DOOR LOCK -LH	TO REPAIR SEE LABOUR	320.00	-
1	FRONT HEADLAMP -LH	CUT	858.40	858.40
1	FRONT TOP STEP GARNISH -LH	SERVICEABLE	185.30	-
1	SET FRONT STEP GARNISH CLIP	NOT NECESSARY	30.00	-
1	FRONT BUMPER FOG LAMP -LH	CRACKED	380.50	380.50
1	FRONT SIDE LAMP -LH	CUT	185.90	185.90
1	FRONT DOOR STICKER	NOT NECESSARY	30.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	480.50	-
1	FRONT GRILLE	SERVICEABLE	280.50	-
	LESS 10% DISCOUNT		-	-226.98
			6,489.20	2,042.82
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF FRONT CORNER FENDER -LH ,FRONT DOOR -LH ,FRONT DOOR HINGE TOP AND FRONT DOOR LOCK -LH		1,200.00	250.00

Report Ref No. CC4/FCI20008678/Kes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION .		1,000.00	320.00
	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL.	NOT NECESSARY	80.00	-
	TO REMOVE /TRANSFER FRONT DOOR COMPONENTS .	NOT NECESSARY	100.00	-
	TO CHECK WIRING FUNCTIONS.		60.00	20.00
			2,440.00	590.00
GRAND TOTAL			8,929.20	2,632.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CC4/FCI20008678/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6873L

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 6873L

RE-INSPECTION

