

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20008685/T1CF3E2**Date:** 05/08/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80409446AVW
Claimant Vehicle No :	GBH1775A	Insured Vehicle No :	SKL711M
Date of Loss:	18/08/2020	Nature of Claim:	TP
		Claim No:	627466

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH1775A	Engine No:	K9KE628D417719
Make & Model:	NISSAN NV200, 1.5 (M)	Chassis No:	VSKYBAM20Z0156614
Reg. Date:	06/03/2018 (Man. Year: 2017)	Odometer:	48808 km
Colour:	Grey		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,100.76	4,607.28	1,493.48	24.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	2,090.00	940.00	31.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,130.76	6,697.28	2,433.48	26.65
+ GST 7.00/7.00% (S\$)	639.15	468.81	170.34	26.65
Nett Amount (S\$)	9,769.91	7,166.09	2,603.82	26.65

INSPECTION

Date of Assignment:	19/08/2020	Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected:	20/08/2020 Inspected At:	50 Bukit Batok Street 23,, #01-06 Midview Building
Estimated Period of Repair:	7.0 days	Singapore 659578

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Aug 2021)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1775A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE N/S	Bent	1,336.00 FN	*1,336.00 FN
2	1		*REAR TAILGATE LOCK N/S	Bent	138.00 FN	*138.00 FN
3	2		*REAR TAILGATE HINGE N/S	Repair	210.00 FN	*- FN
4	1		*REAR TAILGATE INNER TRIM N/S	Not Necessary	342.00 FN	*- FN
5	1		*NV200	Necessary	88.00 FN	*88.00 FN
6	1		*EMBLEM	Necessary	145.60 FN	*145.60 FN
7	1		*REAR TAILGATE O/S	Bent	1,504.90 FN	*1,053.70 FN
8	1		*REAR TAILGATE LOCK O/S	Bent	138.00 FN	*138.00 FN
9	2		*REAR TAILGATE HINGE O/S	Repair	210.00 FN	*- FN
10	1		*REAR TAILGATE INNER TRIM O/S	Not Necessary	342.00 FN	*- FN
11	1		*REAR BUMPER	Deformed	700.80 FN	*700.80 FN
12	2		*REAR BUMPER RETAINER	Not Necessary	82.00 FN	*- FN
13	1		*REAR BUMPER SPONGE	Deformed	145.20 FN	*145.20 FN
14	1		*REAR END PANEL INNER	Bent	485.40 FN	*485.40 FN
15	1		*REAR END PANEL OUTER	Bent	268.00 FN	*268.00 FN
16	1		*REAR END PANEL TOP GARNISH	Deformed	165.50 FN	*165.50 FN
17	1		*REAR RUBBER	Cut	105.00 FN	*105.00 FN
18	10		*CLIPS	Necessary	40.00 FS	*40.00 FS
19	1		*SET REAR SENSOR	Not Working	220.00 FS	*200.00 FS
20	1		*6PAX	Necessary	15.00 FS	*15.00 FS
21	3		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	6,741.40	5,084.20
- Nett Item Discount on N Items 10.00/10.00% (\$)	640.64	476.92
Total Parts (\$)	6,100.76	4,607.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPAIR, REPLACE & INSTALL FRONT DAMAGED PARTS	New	1,500.00	1,000.00
2	TO R & R REAR WINDSCREEN GLASS	New	250.00	160.00
3	TO R & R SENSOR WIRING	New	80.00	30.00
4	TO PUTTY & SPRAY PAINTING	New	1,200.00	900.00
Gross Labour Cost (\$\$)			3,030.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >