

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20008687/KYF3E2  
**Date:** 24/09/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001193653
Claimant Vehicle No : SLK2224H	Insured Vehicle No :	SLM7487Y
Date of Loss: 14/08/2020	Nature of Claim:	TP Claim No: 246790

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2224H	Engine No:	L15B3537783
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Chassis No:	GK81006624
Reg. Date:	10/01/2017 (Man. Year: 2016)	Odometer:	93186 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 4 mm	Rear Left Side:	KAPSEN 3 mm
Front Right Side:	KAPSEN 4 mm	Rear Right Side:	KAPSEN 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,919.40	2,600.28	2,319.12	47.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	950.00	2,250.00	70.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,119.40</b>	<b>3,550.28</b>	<b>4,569.12</b>	<b>56.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,119.40</b>	<b>2,800.00</b>	<b>5,319.40</b>	<b>65.51</b>

### INSPECTION

Date of Assignment:	19/08/2020	
Date Inspected:	20/08/2020 Inspected At:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Singapore 575645
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,289.84 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Sep 2020)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK2224H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE OUTER HANDLE	* Check	383.10 FL	*- FL
3	1		*REAR TAILGATE EMBLEM H	Necessary	27.90 FL	*27.90 FL
4	1		*REAR TAILGATE EMBLEM SHUTTLE	Necessary	55.00 FL	*55.00 FL
5	1		*REAR TAILGATE RUBBER	Distorted / Dented	168.50 FL	*168.50 FL
6	2		*REAR TAILGATE ABSORBER	Serviceable	313.80 FL	*- FL
7	1		*REAR TAILGATE INNER GARNISH	* Check	320.00 FL	*- FL
8	1		*REAR TAILGATE LOCK UPPER	Dented	157.10 FL	*157.10 FL
9	2		*REAR TAIL GATE REFLECTOR	Serviceable	721.60 FL	*- FL
10	2		*REAR TAILEND PANEL TEROSTAT SEALANT	* Check	108.40 FL	*- FL
11	1		*REAR TAILEND PANEL	* Check	560.80 FL	*- FL
12	1		*REAR BUMPER	Buckled	1,150.60 FL	*1,150.60 FL
13	2		*REAR BUMPER RETAINER	Serviceable	73.00 FL	*- FL
14	2		*REAR BUMPER SPONGE / SIDE	Serviceable	113.00 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	* Check	90.00 FL	*- FL
16	2		*REAR BUMPER REFLECTOR COVER	Serviceable	90.20 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Dented	17.00 FL	*17.00 FL
18	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
19	1		*REAR W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
20	1		*REAR W/SCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
21	1		*REAR NO PLATE (EMBOSS) + HOLDER	Dented	55.00 FS	*45.00 FS
22	20		*CLIPS	Necessary	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,028.00</b>	<b>3,154.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,108.60	553.82
<b>Total Parts (\$)</b>	<b>4,919.40</b>	<b>2,600.28</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE FOR REMOVAL & REFIX REAR W/SCREEN GLASS	New	150.00	120.00
2	TO CHECK WATER SEEPAGE	New	60.00	20.00
3	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	New	80.00	50.00
4	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS (* Check)	New	120.00	0.00
5	TO REPAIR, RE-ALIGN ON REAR EXHAUST SILENCER	New	120.00	0.00
6	LABOUR TO REMOVE / REFIX REAR SEAT, INTERIOR GARNISH IN FACILATES REPAIR JOB	New	120.00	60.00
7	MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB	New	350.00	0.00
8	TO REPAIR, PANEL BEAT, STRAIGHTEN, ALIGN ON REAR FLOOR PANEL & AFFECTED AREA. TO CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACED PANEL & LABOUR TO REPLACED THE ABOVE MENTIONED PARTS (* Check)	New	1,000.00	0.00
9	TO PUTTY, PRIMER & SPRAY PAINT ON REAR TAILGATE, REAR END PANEL, REAR FLOOR PANEL, REAR BUMPER & REAR REVERSE SENSOR USING 2K PAINT	New	1,200.00	700.00
<b>Gross Labour Cost (S\$)</b>			<b>3,200.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >