

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008690/GQF3E2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900036415
Claimant Vehicle No : SGH2616K	Insured Vehicle No : SKP5518B
Date of Loss: 17/08/2020	Nature of Claim: TP Claim No: 0523563529SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH2616K		
Make & Model:	DAIHATSU TERIOS, 1.5		Engine No: HIDDEN
Reg. Date:	03/06/2006 (Man. Year: 2006)		Chassis No: JDAJ210G001007065
Colour:	Grey	Odometer:	284152 km
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/08/2020	
Date Inspected:	20/08/2020 Inspected At:	King's Auto Air-conditioning (HQ) Blk 176 Sin Ming Dr #02-10 Singapore 575721 Singapore 575721
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
6	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
7	1		*FRT GRILLE	Broken	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT SUPPORT PANEL	Buckled	0.00 F	*- F
10	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
11	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
12	1		*BONNET	Repair	0.00 F	*- F
13	1		*BONNET LOCK	Bent	0.00 F	*- F
14	1		*AIR CON CONDENSER	Cut	0.00 F	*- F
15	1		*REAR NUMBER PLATE BASE	Scratched	0.00 F	*- F
16	1		*REAR BUMPER	Deformed	0.00 F	*- F
17	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
18	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
19	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
20	1		*REAR END PANEL	Repair	0.00 F	*- F
21	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
22	1		*TAILGATE	Buckled	0.00 F	*- F
23	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
24	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
25	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
26	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
27	2		*SPARE TYRE COVER	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >