

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008696/R1GS3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100471552
Claimant		
Vehicle No : SLD6856U	Insured Vehicle No :	SLD3620C
Date of Loss: 18/08/2020	Nature of Claim: TP	Claim No: 8479904275SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6856U		
Make & Model:	VOLKSWAGEN GOLF VARIANT, 1.4 R-LINE (A)	Engine No:	CZC086166
Reg. Date:	27/06/2016 (Man. Year: 2015)	Chassis No:	WVWZZZAUZGP578450
Colour:	Grey	Odometer:	84620 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,684.27	1,791.86	5,892.41	76.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,000.00	3,280.00	5,720.00	63.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,684.27	5,071.86	11,612.41	69.60
+ GST 7.00/7.00% (\$\$)	1,167.90	355.03	812.87	69.60
Nett Amount (\$\$)	17,852.17	5,426.89	12,425.28	69.60
+ Car Rental (3.0 x S\$85.60/day) (\$\$)		256.80		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,685.69		

INSPECTION

Date of Assignment:	20/08/2020	
Date Inspected:	20/08/2020	Inspected At:
		Volkswagen Centre Singapore (HQ)
		247 Alexandra Road
		Singapore 159934
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*1K WINDOW ADHESIVE	Not Necessary	99.02 FS	*- FS
2	1		*ALL PURPOSE CLEANER	Not Necessary	89.22 FS	*- FS
3	1		*PRIMER	Not Necessary	25.74 FS	*- FS
4	1		*ACTIVATOR FOR PRECOATED W	Not Necessary	23.77 FS	*- FS
5	2		*APPLICATOR	Not Necessary	18.78 FS	*- FS
6	1		*REAR TRUNK LID	Not Necessary	2,044.18 FS	*- FS
7	1		*SPOILER BLACK	Not Necessary	151.37 FS	*- FS
8	1		*SPOILER BLACK	Not Necessary	151.37 FS	*- FS
9	1		*PACKING ADHESIVE RR NUMBER PLATE PACKING	Not Necessary	27.82 FS	*- FS
10	2		*RIVETTED CAP NUT	Not Necessary	4.46 FS	*- FS
11	1		*OPER MECHAN WITH MICRO SW	Not Necessary	1,916.99 FS	*- FS
12	1		*INSCRIPTION BRIGHT CHROME NAME PLATE (GOLF)	Not Necessary	68.12 FS	*- FS
13	1		*INSCRIPTION BRIGHT CHROME NAME PLATE (230 TSI)	Not Necessary	66.37 FS	*- FS
14	1		*COVER FOR BUMPER PRIMED	Deformed	1,189.69 FS	*1,189.69 FS
15	1		*1 SET SENSOR BRACKETS PRI	Necessary	21.89 FS	*21.89 FS
16	1		*SENSOR BRACKET	Necessary	13.86 FS	*13.86 FS
17	1		*SENSOR BRACKET	Necessary	13.86 FS	*13.86 FS
18	2		*SENSOR BRACKET	Necessary	27.72 FS	*27.72 FS
19	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
20	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
21	1		*REAR DIFFUSOR BLACK REAR SPOILER	Deformed	330.28 FS	*330.28 FS
22	1		*BUMPER REINFORCEMENT	Not Necessary	619.61 FS	*- FS
23	1		*ATTACHMENT STRIP BUMPER CENTRE BRACKET	Cracked	59.22 FS	*59.22 FS
24	1		*GUIDE PIECE TAILLIGHT LOWER BRACKET LH	Not Necessary	36.24 FS	*- FS
25	1		*GUIDE PIECE TAILLIGHT LOWER BRACKET RH	Not Necessary	36.24 FS	*- FS
26	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	36.24 FS	*- FS
27	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	36.24 FS	*- FS
28	1		*REFLECTOR LH	Not Necessary	65.92 FS	*- FS
29	1		*REFLECTOR RH	Not Necessary	65.92 FS	*- FS
30	1		*ADDITIONAL BRAKE LIGHT WI	Not Necessary	158.79 FS	*- FS
31	1		*REAR WATER LEAK TEST	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,684.27** **1,791.86**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	480.00	0.00
2	DIAGNOSTIC AND PROGRAMMING	New	280.00	0.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINT	New	3,200.00	1,600.00
5	R&R REAR W/SCREEN	New	840.00	0.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	0.00
Gross Labour Cost (\$)			9,000.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >