



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104930

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 13/07/2021
Reference CC4/FCI20008698/Ara3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMM 4921T
Insured Veh. SHA 9380T
Claim No. D20003249MFSH
Policy No. D-20094921MFSH
Accident Date 14/08/2020
Inspection Date 19/08/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20008698/Ara3q2	
			Date: 13/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9380T	Veh. Inspected	SMM 4921T	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003249MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	18/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN ELGRAND	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1TBAE52Z0802498	Colour	WHITE	
Odometer	45467 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	MICHELIN	6 mm	
L/H Front Tyre	225/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2020	Inspection Date	19/08/2020	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 4921T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR AIR CONDITIONER COOLING UNIT	CRACKED	2,931.00	2,931.00
1	REAR BUMPER	DISTORTED	933.35	848.50
1	REAR BUMPER INNER SPONGE	CRACKED	155.50	155.50
2	REAR BUMPER LH INNER SPONGE @ \$55.00	CRACKED	110.00	55.00
2	REAR BUMPER REFLECTOR L/R @ \$61.90	CRACKED	123.80	123.80
1	REAR BUMPER REINFORCEMENT	BENT	813.05	720.50
2	REAR BUMPER REINFORCEMENT BRACKET L/R @ \$155.20	BENT	310.40	170.00
2	REAR BUMPER SIDE RETAINER L/R @ \$39.35	DAMAGED	78.70	78.70
1	REAR END PANEL	DISTORTED	825.90	825.90
1	REAR END PANEL ANTENNA SENSOR	CRACKED	73.35	73.35
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	357.50	357.50
2	REAR END SIDE PANEL L/R @ \$96.50	TO REPAIR SEE LABOUR	193.00	-
1	REAR EXHAUST SILENCER BOX	BENT	956.35	910.80
1	REAR EXHAUST SILENCER GASKET	NECESSARY	15.00	15.00
3	REAR EXHAUST SILENCER RUBBER MOUNTING @ \$20.00	NOT NECESSARY	60.00	-
2	SET REAR FENDER INNER TRIM GARNISH CLIPS L/R @ \$50.00	NECESSARY	100.00	60.00
2	REAR FENDER INNER TRIM GARNISH L/R @ \$938.85	CRACKED	1,877.70	1,768.00
1	REAR FLOOR PANEL	DISTORTED	1,187.35	1,187.35
1	REAR FLOOR PANEL INNER TOP TRIM CARPET	TORN	572.00	411.00
1	REAR FLOOR PANEL INNER TRIM BOARD COVER	DEFORMED	484.00	360.90
4	REAR FLOOR PANEL RAIL BRACKET @ \$55.00	NOT NECESSARY	220.00	-
2	REAR LOWER TAILLAMP L/R @ \$684.05	CRACKED	1,368.10	1,332.00
1	REAR SEAT FRAME INNER TOP COVER	CRACKED	506.00	506.00
1	REAR TAILGATE	DISTORTED	2,572.90	2,572.90
1	REAR TAILGATE 'HIGHWAY STAR' EMBLEM	NECESSARY	55.90	55.90
1	REAR TAILGATE CLOSING BUTTON SWITCH	NOT NECESSARY	62.00	-
2	REAR TAILGATE DAMPER L/R @ \$255.00	NOT NECESSARY	510.00	-
1	REAR TAILGATE INNER PULL GARNISH	NOT NECESSARY	29.00	-

Report Ref No. CC4/FCI20008698/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE INNER TRIM GARNISH	DEFORMED	580.80	580.80
1	REAR TAILGATE MECHANISM LOCK	JAMMED	675.07	675.07
1	REAR TAILGATE MECHANISM LOCK MOTOR	JAMMED	1,608.75	585.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	NOT NECESSARY	34.90	-
1	REAR TAILGATE OUTER CHROME MOULDING	CRACKED	924.00	458.00
1	REAR TAILGATE RH REFLECTOR	CRACKED	147.15	147.15
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R @ \$20.00	NOT NECESSARY	40.00	-
2	REAR TAILGATE SIDE SENSOR MOULDING L/R @ \$471.60	NOT NECESSARY	943.20	-
1	REAR TAILGATE WEATHER STRIP	CUT	239.69	239.69
2	REAR TAILLAMP LOWER GARNISH L/R @ \$180.00	O/S DEFORMED	360.00	180.00
	LESS 10% DISCOUNT		-2,303.54	-1,838.53
			20,731.87	16,546.78
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NECESSARY	300.00	200.00
2	SET REAR LOWER TAILLAMP CLIPS L/R @ \$20.00 (SN)	NECESSARY	40.00	40.00
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR TAILGATE OUTER CHROME MOULDING CLIPS (SN)	NECESSARY	30.00	10.00
1	REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	60.00
2	SET REAR TAILLAMP LOWER GARNISH CLIPS L/R @ \$20.00 (SN)	NECESSARY	40.00	40.00
			920.00	620.00
	<u>LABOUR</u>			
	TO REMOVE, REPLACED AIRCON EVAPORATOR UNIT, AIRCON BLOWER MOTOR AND ETC TO VACUUM SYSTEM AND TOP UP GAS.		250.00	180.00
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	280.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		60.00	60.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		150.00	120.00

Report Ref No. CC4/FCI20008698/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSETRY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		180.00	150.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,000.00	1,400.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		150.00	80.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END SIDE PANEL L/R.		2,200.00	1,300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	120.00
	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
			5,470.00	3,490.00
GRAND TOTAL			27,121.87	20,656.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,500.00

Report Ref No. CC4/FC120008698/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4921T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4921T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4921T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4921T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4921T

RE-INSPECTION

