

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008702/APA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800065856

Claimant
Vehicle No : SKQ7859Z **Insured Vehicle No :** SJX5571R

Date of Loss: 18/08/2020 Nature of Claim: TP Claim No: 7170777292SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ7859Z		
Make & Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Engine No:	CJE090093
Reg. Date:	26/12/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8K8FA046294
Colour:	Bronze	Odometer:	83033 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R16	Rear Tyre Size:	225/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,297.00	2,239.76	2,057.24	47.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,719.00	3,761.76	2,957.24	44.01
+ GST 7.00/7.00% (S\$)	470.33	263.32	207.01	44.01
Nett Amount (S\$)	7,189.33	4,025.08	3,164.25	44.01
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,327.08		

INSPECTION

Date of Assignment: 21/08/2020

Date Inspected: 21/08/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,273.00 FS	*1,818.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	225.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	264.00 FS	*210.80 FS
4	1		*REAR BUMPER CARRIER	Not Necessary	636.00 FS	*- FS
5	2		*REAR BUMPER BRACKET HOLDER -LH/RH	Not Necessary	440.00 FS	*- FS
6	1		*REAR BUMPER SECURING STRIP	Necessary	14.00 FS	*10.56 FS
7	1		*REAR BUMPER GUIDE SECTION -LH UPPER	Not Necessary	23.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION -RH UPPER	Not Necessary	22.00 FS	*- FS
9	1		*REAR PARKING AID SENSOR	Damaged	200.00 FS	*200.00 FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,297.00** **2,239.76**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER AND REAR BUMPER SPOILER .TO INSPECT REAR END PANELLING .RE-ORGANISE CRASH MANAGEMENT COMPONENTS ,REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >