

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20008703/T1DA3Q2

**Date:** 07/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800137065

**Claimant**  
**Vehicle No :** SLP6871L **Insured Vehicle No :** SJM1907R

Date of Loss: 17/08/2020 Nature of Claim: TP Claim No: 6949263078SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLP6871L</b>	Engine No:	3ZZ4817067
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106125201
Reg. Date:	18/02/2009 (Man. Year: 2008)	Odometer:	138865 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	832.90	680.15	152.75	18.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	430.00	400.00	48.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,662.90</b>	<b>1,110.15</b>	<b>552.75</b>	<b>33.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	1,662.90	900.00	762.90	45.88
<b>+ GST 7.00/7.00% (S\$)</b>	116.40	63.00	53.40	45.88
<b>Nett Amount (S\$)</b>	<b>1,779.30</b>	<b>963.00</b>	<b>816.30</b>	<b>45.88</b>
<b>+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		385.20		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,350.20</b>		

### INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)  
50 Bukit Batok Street 23,, #01-06  
Midview Building  
Singapore 659578

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	484.90 FL	*484.90 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	177.00 FL	*- FL
3	1		*REAR BUMPER SPONGE	Deformed	155.30 FL	*155.30 FL
4	1		*SET REAR BUMPER SENSOR	Not Working	220.00 FS	*200.00 FS
					<b>Sub Total (S\$)</b>	<b>1,037.20</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>204.30</b>
					<b>Total Parts (S\$)</b>	<b>832.90</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	350.00	200.00
2	TO R&R SENSOR WIRING	New	80.00	30.00
3	TO PUTTY & SPRAY PAINTING	New	400.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>830.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**