

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008705/ERA3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100396287-05

Claimant
Vehicle No : GBE1028P **Insured Vehicle No :** GBD5626S

Date of Loss: 17/08/2020 Nature of Claim: TP Claim No: 5219397541SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE1028P		
Make & Model:	MERCEDES-BENZ VITO 114, 2.1 CDI PANEL VAN LONG ABS 5DR (A)	Engine No:	65195033164927
Reg. Date:	26/01/2016 (Man. Year: 2015)	Chassis No:	WDF44760323109949
Colour:	Grey	Odometer:	46820 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,811.79	3,028.30	1,783.49	37.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,709.92	680.00	1,029.92	60.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,521.71	3,708.30	2,813.41	43.14
+ GST 7.00/7.00% (S\$)	456.52	259.58	196.94	43.14
Nett Amount (S\$)	6,978.23	3,967.88	3,010.35	43.14
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,375.33		

INSPECTION

Date of Assignment: 19/08/2020

Date Inspected: 27/08/2020 Inspected At:

Autoclinic Pte Ltd (HQ)
48 TOH GUAN ROAD EAST #02-136
ENTERPRISE HUB SINGAPORE
608586
Singapore 608586

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR	Dented	2,461.00 FL	*2,461.00 FL
2	1		*REAR GLASS PANEL	Broken	1,248.60 FL	*1,248.60 FL
3	2		*HINGE LEFT & RIGHT TAIL GATE	Not Necessary	385.20 FL	*- FL
4	4		*BRACKET FOR LEFT & RIGHT GAS -FILLED TELESCOPIC STRUT (TOP & BOTTOM)	Not Necessary	239.68 FL	*- FL
5	2		*GAS PRESSURE STRUT LEFT & RIGHT	Not Necessary	255.60 FL	*- FL
6	6		*HEXALOBULAR BOLT FASTENER ,HINGE AT BODY	Not Necessary	73.20 FL	*- FL
7	6		*HEXALOBULAR BOLT FASTENER ,HINGE TO TAILGATE	Not Necessary	37.20 FL	*- FL
8	1		*REAR WIPER MOTOR	Not Necessary	489.80 FL	*- FL
9	1		*REAR WIPER ARM	Not Necessary	140.10 FL	*- FL
10	1		*REAR WIPER BLADE	Not Necessary	85.60 FL	*- FL
11	1		*REAR DOOR LOCK ASSY	Not Necessary	323.09 FL	*- FL
12	1		*REAR DOOR PANEL INNER TRIM COVER	Not Necessary	348.52 FL	*- FL
13	1		*VITO EMBLEM	Necessary	42.80 FS	*42.80 FS
14	1		*CENTRE LOGO EMBLEM	Necessary	49.22 FS	*49.22 FS
15	1		*114 LOGO EMBLEM	Necessary	63.13 FS	*63.13 FS
16	1		*BLUETEC LOGO	Necessary	65.27 FS	*65.27 FS
17	1		*70KM/H DECAL	Necessary	12.84 FS	*12.84 FS
18	1		*6 PAX DECAL	Necessary	12.84 FS	*12.84 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,333.69	3,955.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,521.90	927.40
Total Parts (\$)	4,811.79	3,028.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR WORKS FOR SPRAY PAINTING	New	600.00	280.00
2	CHECK WIRING AND LIGHTING	New	80.00	50.00
3	LABOUR TO REMOVE AND REFIT REAR PANEL PARTS	New	600.00	350.00
4	REAR BUMPER CHASSIS AND UNDERCARRIAGE PANEL BEATING	New	350.00	0.00
5	REAR LICENSE PLATE +LICENSE PLATE FRAME	New	20.00	0.00
6	LICENSE PLATE LIGHT	New	59.92	0.00
Gross Labour Cost (\$\$)			1,709.92	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >