

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20008707/UPA3Q2

**Date:** 19/01/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993943  
**Claimant**  
**Vehicle No :** SMN385L **Insured Vehicle No :** SMG4972C  
Date of Loss: 17/08/2020 Nature of Claim: TP Claim No: 0725349733SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN385L**  
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4021006  
Reg. Date: 22/10/2015 (Man. Year: 2015) Chassis No: RU11101002  
Colour: White Odometer: 52841 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,902.80	4,857.44	2,045.36	29.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,680.00	1,060.00	38.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,642.80</b>	<b>6,537.44</b>	<b>3,105.36</b>	<b>32.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,642.80</b>	<b>5,200.00</b>	<b>4,442.80</b>	<b>46.07</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,607.45</b>		

#### INSPECTION

Date of Assignment: 20/08/2020  
Date Inspected: 20/08/2020 Inspected At: Quan De Motor Trading  
BLK 1 KAKI BUKIT AVENUE 6 #01-67  
AUTOBAY SINGAPORE 417883  
Singapore 417883  
Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 FL	*121.30 FL
2	1		*TAILGATE	Badly Dented	953.00 FL	*953.00 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
4	1		*TAILGATE INNER LOCK	Twisted /Shorted	198.50 FL	*198.50 FL
5	1		*TAILGATE INNER TRIM BOARD	Serviceable	321.70 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	148.50 FL	*148.50 FL
7	1		*REAR BUMPER	Deformed	566.20 FL	*566.20 FL
8	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	71.00 FL	*- FL
9	1		*REAR BUMPER SIDE	Deformed / Torn	235.10 FL	*235.10 FL
10	1		*REAR BUMPER LOWER DIFFUSER	Twisted	348.20 FL	*348.20 FL
11	1		*REAR END PANEL	Badly Dented	514.00 FL	*514.00 FL
12	1		*REAR END PANEL TOP GARNISH	Torn	166.80 FL	*166.80 FL
13	2		*TAILLAMPS	Scratched / Cracked	901.00 FL	*901.00 FL
14	1		*REAR FLOOR PANEL	Repair	912.30 FL	*- FL
15	1		*REAR FLOOR PANEL TOP BOARD	Torn	388.20 FL	*388.20 FL
16	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	522.30 FL	*522.30 FL
17	1		*REAR FENDER OUTER PROTECTOR	O/S Twisted	430.00 FL	*215.00 FL
18	1		*REAR EXHAUST	Not Necessary	899.20 FL	*- FL
19	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
21	1		*REAR SPOILER	Warped	300.00 FS	*300.00 FS
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,453.50</b>	<b>5,924.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,550.70	1,066.86
<b>Total Parts (\$)</b>	<b>6,902.80</b>	<b>4,857.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	1,000.00	600.00
7	SPRAY PAINTING	New	1,200.00	750.00
			<b>Gross Labour Cost (\$)</b>	<b>2,740.00</b>
				<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >