

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20008708/KVF3E2

**Date:** 10/11/2020

#### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-504432-WTT
<b>Claimant Vehicle No :</b>	EV58J	<b>Insured Vehicle No :</b>	FBQ3054L
Date of Loss:	15/08/2020	Nature of Claim:	TP
		Claim No:	MSC/V/20-000671

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EV58J	Engine No:	HR12117412B
Make & Model:	NISSAN NOTE, 1.2 DIG-S CVT (A)	Chassis No:	JN1TBAE12Z0982103
Reg. Date:	20/08/2015 (Man. Year: 2015)	Odometer:	45739 km
Colour:	Metallic Silver		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,014.80	2,101.50	2,913.30	58.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,080.00	1,350.00	39.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,444.80</b>	<b>4,181.50</b>	<b>4,263.30</b>	<b>50.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>591.14</b>	<b>292.71</b>	<b>298.43</b>	<b>50.48</b>
<b>Nett Amount (S\$)</b>	<b>9,035.94</b>	<b>4,474.21</b>	<b>4,561.73</b>	<b>50.48</b>

#### INSPECTION

Date of Assignment:	19/08/2020	
Date Inspected:	24/08/2020	Inspected At:
		MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	7.0 days	

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$442.80 NETT)

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2020)
<b>Parts:</b> 144	NISSAN NOTE 1.2 DIG-S CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for EV58J)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE MIRROR	Dented/Cracked	684.00 FL	*684.00 FL
2	1		*LH SIDE MIRROR COVER	Repair	176.00 FL	*- FL
3	1		*LH SIDE MIRROR SIGNAL LAMP	*Check	199.00 FL	*- FL
4	1		*LH SIDE MIRROR MOTOR	*Check	293.00 FL	*- FL
5	1		*FRONT BUMPER	Repair	939.00 FL	*- FL
6	1		*FRONT LH FENDER	Repair	604.00 FL	*- FL
7	1		*FRONT LH FENDER INNER SHIELD	Distorted	140.00 FL	*140.00 FL
8	10		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*60.00 FL
9	1		*FRONT LH DOOR	Bent	966.00 FL	*966.00 FL
10	1		*REAR LH DOOR	Repair	966.00 FL	*- FL
11	1		*LH ROCKER PANEL	Bent	485.00 FL	*485.00 FL
12	1		*BUMPER CLIPS	Not Necessary	60.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,572.00</b>	<b>2,335.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	557.20	233.50
<b>Total Parts (\$\$)</b>	<b>5,014.80</b>	<b>2,101.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS,INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	750.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	100.00	60.00
3	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	240.00	60.00
4	TO APPLY ANTI RUST COATING	New	150.00	30.00
5	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	60.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	0.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	1,100.00
<b>Gross Labour Cost (S\$)</b>			<b>3,430.00</b>	<b>2,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >