

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20008711/GQF3N2**Date:** 01/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM20D202931
<b>Claimant Vehicle No :</b>	SMJ4186P	<b>Insured Vehicle No :</b>	SKD7190L
Date of Loss:	15/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202931/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMJ4186P</b>		
Make & Model:	MERCEDES-BENZ A250, 2.0 SPORT (R18 LED SR) (A)	Engine No:	27092030439301
Reg. Date:	01/09/2014 (Man. Year: 2014)	Chassis No:	WDD1760442J293261
Colour:	Grey	Odometer:	113883 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/35 ZR19	Rear Tyre Size:	235/35 ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,774.17	3,080.44	15,693.73	83.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	520.00	2,960.00	85.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,254.17</b>	<b>3,600.44</b>	<b>18,653.73</b>	<b>83.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,850.00</b>		
<b>(S\$)</b>	22,254.17	2,850.00	19,404.17	87.19
<b>+ GST 7.00/7.00% (S\$)</b>	1,557.79	199.50	1,358.29	87.19
<b>Nett Amount (S\$)</b>	<b>23,811.96</b>	<b>3,049.50</b>	<b>20,762.46</b>	<b>87.19</b>

**INSPECTION**

Date of Assignment:	19/08/2020	
Date Inspected:	20/08/2020	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2021)

**Parts:** 144 MERCEDES-BENZ A250 2.0 SPORT (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMJ4186P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,589.85 FL	*1,031.53 FL
2	1	*FRONT BUMPER RETAINER (LHS)	Not Necessary	268.85 FL	*- FL
3	1	*FRONT BUMPER RETAINER (RHS)	Not Necessary	268.85 FL	*- FL
4	1	*FRONT BUMPER GRILLE	Deformed	1,164.90 FL	*508.13 FL
5	1	*FRONT BUMPER GRILLE EMBLEM	Not Necessary	358.90 FL	*- FL
6	1	*FRONT BUMPER LOGO	Cracked	1,613.25 FL	*55.10 FL
7	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	989.73 FL	*- FL
8	4	*FRONT BUMPER REVERSE SENSOR	Not Necessary	1,533.20 FL	*- FL
9	1	*FRONT BUMPER SIDE GRILLE (LHS)	Not Necessary	212.85 FL	*- FL
10	1	*FRONT REINFORCEMENT (NPA)	Not Necessary	0.00 FL	*- FL
11	1	*FRONT BUMPER SPONGE	Cracked	212.33 FL	*108.17 FL
12	1	*FRONT CHASSIS PANEL (LHS)(NPA)	Not Necessary	0.00 FL	*- FL
13	1	*FRONT CHASSIS PANEL (RHS)(NPA)	Not Necessary	0.00 FL	*- FL
14	1	*HEADLIGHT (LHS)	Broken	3,529.85 FL	*764.23 FL
15	1	*HEADLIGHT (RHS)	Not Necessary	3,529.85 FL	*- FL
16	1	*FRONT SUPPORT PANEL (NPA)	Not Necessary	0.00 FL	*- FL
17	10	*FRONT BUMPER CLIP	Necessary	90.00 FS	*30.00 FS
18	1	*FRONT BUMPER REVERSE SENSOR	Not Necessary	9.00 FS	*- FS
19	1	*FRONT BUMPER LOWER LIP (CARBON FIBRE)	Cracked	2,500.00 FS	*800.00 FS
20	1	*FRONT BUMPER SIDE UPPER SPOILER (CARBON FIBRE)	Not Necessary	350.00 FS	*- FS
21	1	*FRONT BUMPER SIDE LOWER SPOILER (CARBON FIBRE)	Not Necessary	350.00 FS	*- FS
22	1	*FRONT NO PLATE	Scratched	50.00 FS	*30.00 FS
23	1	*RADAR	Not Necessary	780.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$)** 20,401.41 3,327.16  
**- List Item Discount on L Items 10.00/10.00% (S\$)** 1,627.24 246.72

**Total Parts (S\$)** 18,774.17 3,080.44

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS	New	800.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	600.00	250.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	150.00	30.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	60.00	0.00
5	RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	80.00	0.00
6	TO SUPPLY UNDER COATING/PUTTY ON PARTS REPLACED	New	80.00	0.00
7	TO CONDUCT HEADLIGHT FOCUS	New	150.00	0.00
8	TO REMOVE & REFIT REAR SENSOR	New	60.00	40.00
9	TO PROGRAMMING RADAR	New	1,500.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,480.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >