

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008712/EPA3Q2

**Date:** 12/11/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>	<b>Insured Vehicle No :</b>	SHD7291P
<b>Vehicle No :</b> SKS225M		
Date of Loss: 18/08/2020	Nature of Claim: TP	Claim No: MCT20080274

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKS225M</b>	
Make & Model:	MAZDA BIANTE, 2.0 BIANTE 5-DOOR WAGON SP.6E (A)	Engine No: PE30599957
Reg. Date:	12/03/2014 (Man. Year: 2013)	Chassis No: JM6CC1071E0103543
Colour:	White	Odometer: 82464 km
Engine Capacity:	1998 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,201.70	7,419.00	782.70	9.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,170.00	7,030.00	3,140.00	30.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,371.70</b>	<b>14,449.00</b>	<b>3,922.70</b>	<b>21.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>(S\$)</b>	18,371.70	6,000.00	12,371.70	67.34
<b>+ GST 7.00/7.00% (S\$)</b>	1,286.02	420.00	866.02	67.34
<b>Nett Amount (S\$)</b>	<b>19,657.72</b>	<b>6,420.00</b>	<b>13,237.72</b>	<b>67.34</b>
<b>+ Loss of Use (12.0 x S\$80.00/day) (S\$)</b>		960.00		
<b>Nett Liability (S\$)</b>		<b>7,380.00</b>		

#### INSPECTION

Date of Assignment:	20/08/2020		
Date Inspected:	21/08/2020	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	9.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2020)
<b>Parts:</b> M1-MPV	MAZDA BIANTE 2.0 BIANTE 5-DOOR WAGON SP.6E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKS225M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Dented	1,170.50 F	*1,170.50 F	
2	2		*GROMMET ,REAR BUMPER	Necessary	6.40 F	*6.40 F	
3	2		*PIN LOCATOR ,REAR BUMPER	Necessary	8.40 F	*8.40 F	
4	2		*GROMMET, REAR BUMPER	Necessary	9.40 F	*9.40 F	
5	2		*RIVET ,REAR BUMPER	Necessary	7.60 F	*7.60 F	
6	2		*FASTENER ,REAR BUMPER	Necessary	6.40 F	*6.40 F	
7	2		*TAPE PROTECTOR ,REAR BUMPER	Necessary	14.80 F	*14.80 F	
8	1		*STRIPE LHS ,REAR BUMPER	Necessary	86.00 F	*86.00 F	
9	1		*STRIPE RHS ,REAR BUMPER	Necessary	86.00 F	*86.00 F	
10	1		*SPRIPE CENTER ,REAR BUMPER	Necessary	130.10 F	*130.10 F	
11	1		*TAILGATE	Dented	1,699.70 F	*1,699.70 F	
12	2		*VALVE ONEWAY ,TAILGATE	Necessary	27.60 F	*27.60 F	
13	3		*FASTENER ,TAILGATE	Necessary	16.80 F	*16.80 F	
14	3		*FASTENER ,TAILGATE	Necessary	18.60 F	*18.60 F	
15	1		*ORNAMENT ,SKYACTIV	Necessary	117.10 F	*117.10 F	
16	4		*FASTENER ,REAR WINDSCREEN	Necessary	11.20 F	*11.20 F	
17	5		*SPACER, REAR WINDSCREEN	Necessary	64.00 F	*64.00 F	
18	2		*FASTENER, REAR WINDSCREEN	Necessary	16.40 F	*16.40 F	
19	1		*REAR END PANEL	Dented	303.20 F	*303.20 F	
20	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS	
21	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS	
22	1		*LHR TRIM ,TRUNK	Not Necessary	632.70 F	*- F	
23	1		*FINISHER ,TAILGATE	Broken	2,018.60 F	*2,018.60 F	
24	1		*LH TAIL LAMP	Broken	1,117.20 F	*1,117.20 F	
25	1		*TRIM ,END PANEL	Cut	122.30 F	*122.30 F	
26	1		*SHORT CORD	Broken	74.90 F	*74.90 F	
27	1		*ANTENNA & KEYLESS BRACKET	Broken	265.80 F	*265.80 F	
					<b>Total Parts (\$\$)</b>	<b>8,201.70</b>	<b>7,419.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESPRAY REAR BUMPER ,REAR END PANEL AND TAILGATE	New	2,520.00	1,890.00
2	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	180.00	180.00
3	TO REMOVE & REFIT CARPET & TRIM ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	660.00	330.00
4	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
5	TO SUPPLY SEALANT ON THE WINDSCREEN GLASS	New	120.00	120.00
6	TO TRANSFER TAILGATE MECHANISM	New	330.00	200.00
7	TO TRANSFER REVERSE SENSORS (WITH REVERSE SENSOR )	New	660.00	330.00
8	TO TRANSFER REVERSE CAMERA (WITH REVERSE CAMERA)	New	660.00	330.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
10	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	120.00
11	TO REPROGRAMME ADTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
12	TO REPLACE REAR BUMPER ,REAR END PANEL AND TAILGATE REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,630.00	2,640.00
<b>Gross Labour Cost (S\$)</b>			<b>10,170.00</b>	<b>7,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >