



TRANS EUROKARS PTE LTD

supd / EP
LKK
EUROKARS GROUP

ESTIMATE COST OF REPAIRS

| | | | |
|--|----------------------|---|--|
| INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX : | | NAME : Mr Eurokars Leasing ADDRESS : 12 Sungei Kadut Ave Spore 729648 TEL : 88685085 | WIP : 33813 EXCESS : DATE: 18-Aug-20 |
| VEH NO : SKS225M | DATE IN : | CONTACT PERSON : | Ronald 63957875 |
| CHASSIS NO : JM6CC1071E0103543 | MILEAGE : | TYPE OF CLAIM : | THIRD PARTY CLAIM |
| MODEL : BIANTE | DATE REG.: 12-Mar-14 | POLICY NO. : | |

NATURE OF WORKS

| Parts Description | | | | REVISED | PRICES |
|-------------------------|--------------|---|-----------------|-------------|-------------|
| NO | QTY | | | | |
| 1 | 1 | REAR BUMPER / <i>DD</i> | MC275-50-221FBB | | \$ 1,170.50 |
| 2 | 2 | GROMMET, REAR BUMPER / <i>MC</i> | MB01W-51-142B | | \$ 6.40 |
| 3 | 2 | PIN LOCATOR, REAR BUMPER / <i>MC</i> | MGJ6B-50-1K5 | | \$ 8.40 |
| 4 | 2 | GROMMET, REAR BUMPER / <i>MC</i> | MBP4K-50-ES1 | | \$ 9.40 |
| 5 | 2 | RIVET, REAR BUMPER / <i>MC</i> | MA001-50-7C1 | | \$ 7.60 |
| 6 | 2 | FASTENER, REAR BUMPER / <i>MC</i> | MGD7A-50-EA1 | | \$ 6.40 |
| 7 | 2 | TAPE PROTECTOR, REAR BUMPER / <i>MC</i> | MTK48-62-864 | | \$ 14.80 |
| 8 | 1 | STRIPE LHS, REAR BUMPER / <i>MC</i> | MC467-50-888 | | \$ 86.00 |
| 9 | 1 | STRIPE RHS, REAR BUMPER / <i>MC</i> | MC467-50-878 | | \$ 86.00 |
| 10 | 1 | STRIPE CENTER, REAR BUMPER / <i>MC</i> | MC467-50-879 | | \$ 130.10 |
| 11 | 1 | TAILGATE / <i>DD</i> | MC2Y3-62-02XF | | \$ 1,699.70 |
| 12 | 2 | VALVE ONEWAY, TAILGATE / <i>MC</i> | MBBN7-58-867 | | \$ 27.60 |
| 13 | 3 | FASTENER, TAILGATE / <i>MC</i> | MB467-68-AC3 34 | | \$ 16.80 |
| 14 | 3 | FASTENER, TAILGATE / <i>MC</i> | MEG21-51-146 | | \$ 18.60 |
| 15 | 1 | ORNAMENT, SKYACTIV / <i>MC</i> | MC603-51-771A | | \$ 117.10 |
| 16 | 4 | FASTENER, REAR WINDSCREEN / <i>MC</i> | MD204-50-896A | | \$ 11.20 |
| 17 | 5 | SPACER, REAR WINDSCREEN / <i>MC</i> | MGJ6A-50-897 | | \$ 64.00 |
| 18 | 2 | FASTENER, REAR WINDSCREEN / <i>MC</i> | MC273-50-896 | | \$ 16.40 |
| 19 | 1 | REAR END PANEL / <i>DD</i> | MC273-70-750B | | \$ 303.20 |
| TOTAL PARTS | | | | | \$ 3,800.20 |
| TOTAL PARTS COST | | | | | \$ 3,800.20 |
| Labour Description | | | | | |
| 1 | MZ-BR-REAR06 | TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>60</i> | | <i>2640</i> | \$ 3,630.00 |

| | | | | |
|----|--------------|---|----------------|-------------|
| 2 | MZ-SP-SREAR6 | TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE. <i>670</i> | <i>1890</i> | \$ 2,520.00 |
| 3 | MZ-BR-SEALER | TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING | NETT | \$ 180.00 |
| 4 | MZ-BR-TRIMS2 | TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION. | <i>330</i> | \$ 660.00 |
| 5 | MZ-BR-GLASS1 | TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. | NETT | \$ 560.00 |
| 6 | MZ-BR-GLASS2 | TO SUPPLY SEALER ON THE WINDSCREEN GLASS. | NETT | \$ 120.00 |
| 7 | MZ-BR-TAILME | TO TRANSFER TAILGATE MECHANISM. | <i>200</i> | \$ 330.00 |
| 8 | MZ-BR-REVSEN | TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR) | <i>330</i> | \$ 660.00 |
| 9 | MZ-BR-CAMERA | TO TRANSFER REVERSE CAMERA.(WITH REVRSE CAMERA) | <i>330</i> | \$ 660.00 |
| 10 | MZ-BR-PLATE1 | TO SUPPLY NUMBER PLATE. | NETT | \$ 70.00 |
| 11 | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | <i>150</i> | \$ 250.00 |
| 12 | MZ-BR-CAVITY | TO CARRY-OUT BODY CAVITY PRESERVATION. | <i>120</i> | \$ 250.00 |
| 13 | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. | <i>180</i> | \$ 350.00 |
| 14 | MZ-BR-SUNDRI | SUNDRIES. | <i>20</i> NETT | \$ 100.00 |

| | | |
|--------------------|------|--------------|
| TOTAL LABOUR | \$ - | \$ 10,340.00 |
| TOTAL PARTS | \$ - | \$ 3,800.20 |
| TOTAL | \$ - | \$ 14,140.20 |
| LESS EXCESS | \$ - | \$ - |
| TOTAL AFTER EXCESS | \$ - | |
| GST 7% | \$ - | \$ - |
| GRAND TOTAL | \$ - | \$ - |

Steve (LKK)
8322 8813
sterechn@lkk.com

with paper
21/8/20, 3.00pm
P/P
By Bel spy
9 days

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED

ACKNOWLEDGMENT FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
LKK CONSULTANTS, HENCE BY THE PRICE AS WELL AS LABOUR CHARGES.
the price of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorized Signature