

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008713/ATF3Q2

**Date:** 02/11/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00000982000
<b>Claimant Vehicle No :</b>	SLK2517M	<b>Insured Vehicle No :</b>	SJV6138M
Date of Loss:	17/08/2020	Nature of Claim:	TP
		Claim No:	N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2517M	Engine No:	D4FDGH113340
Make & Model:	KIA CARENS, 1.7 (A)	Chassis No:	KNAHU815VG7164499
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	60614 km
Colour:	Black		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,728.06	1,092.73	5,635.33	83.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,235.00	1,090.00	2,145.00	66.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,963.06</b>	<b>2,182.73</b>	<b>7,780.33</b>	<b>78.09</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,700.00</b>		
<b>(\$\$)</b>	9,963.06	1,700.00	8,263.06	82.94
<b>+ GST 7.00/7.00% (\$\$)</b>	697.41	119.00	578.41	82.94
<b>Nett Amount (\$\$)</b>	<b>10,660.47</b>	<b>1,819.00</b>	<b>8,841.47</b>	<b>82.94</b>

### INSPECTION

Date of Assignment:	19/08/2020	
Date Inspected:	20/08/2020 Inspected At:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
<b>Parts:</b>	M1-MPV	KIA CARENS 1.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK2517M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	1,309.80 FL	*- FL
2	1		*REAR FENDER RH	Repair	1,352.90 FL	*- FL
3	1		*REAR FENDER GLASS WITH MOLDING RH	Not Necessary	368.70 FL	*- FL
4	1		*REAR FENDER STONE PROTECTIVE STICKER RH	Necessary	35.80 FL	*35.80 FL
5	1		*REAR FENDER INNER SHIELD RH	Not Necessary	75.60 FL	*- FL
6	1		*REAR SUSPENSION AXLE	Not Necessary	1,001.30 FL	*- FL
7	1		*REAR SUSPENSION SHOCK ABSORBER RH	Not Necessary	232.40 FL	*- FL
8	1		*REAR SUSPENSION WHEEL HUB BEARING RH	Damaged	333.90 FL	*333.90 FL
9	1		*REAR FENDER GLASS WITH MOLDING RH	Not Necessary	368.70 FS	*- FS
10	1		*REAR FENDER INNER SHIELD CLIPS SET RH	Necessary	60.00 FS	*30.00 FS
11	1		*ROCKER SIDE SKIRTING RH (STICK ON)	Repair	680.00 FS	*- FS
12	1		*REAR 17 SPORT RIM RH	Cut	800.00 FS	*480.00 FS
13	1		*REAR 17 TYRE RH	Cut	580.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,199.10</b>	<b>1,129.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	471.04	36.97
<b>Total Parts (\$\$)</b>	<b>6,728.06</b>	<b>1,092.73</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,000.00	200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,000.00	700.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	75.00	30.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	0.00
5	TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	New	250.00	0.00
6	TO DISMANTLE & REINSTALL REAR FENDER GLASS RH PERFORM	New	120.00	0.00
7	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	New	350.00	80.00
8	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	80.00
9	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	180.00	0.00
10	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,235.00</b>	<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >