

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III20008723/EBA3Q2**Date:** 05/11/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SDZ2211K	Insured Vehicle No :	SH9501U
Date of Loss: 19/08/2020	Nature of Claim: TP	Claim No: MCT20080282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ2211K		
Make & Model:	BMW 330I, 2.0 (A)	Engine No:	F0713336B48B20B
Reg. Date:	24/06/2019 (Man. Year: 2019)	Chassis No:	WBA5R120X0AK73114
Colour:	Grey	Odometer:	7212 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	185 R15C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,196.20	1,002.85	193.35	16.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,527.00	1,075.00	452.00	29.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,723.20	2,077.85	645.35	23.70
+ GST 7.00/7.00% (S\$)	190.62	145.45	45.17	23.70
Nett Amount (S\$)	2,913.82	2,223.30	690.52	23.70
+ Loss of Use (1.0 x S\$120.00/day) (S\$)		120.00		
	Nett Liability (S\$)	2,343.30		

INSPECTION

Date of Assignment:	20/08/2020	
Date Inspected:	10/09/2020	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	1.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2020)
Parts: 143	BMW 330I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDZ2211K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*LH OUTSIDE MIRROR COVER CAP PRIMED	Repair	128.10 FS	*- FS
3	1		*LH HEATED OUTSIDE MIRROR	Broken	962.85 FS	*962.85 FS
4	1		*LH AUXILIARY MIRROR TURN INDICATOR	Not Necessary	65.25 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 1,196.20 1,002.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE LEFT DIDE MIRROR ASSEMBLY	New	1,275.00	850.00
2	TO PAINTING LEFT MIRROR COVER	New	75.00	75.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS	New	177.00	150.00
Gross Labour Cost (\$\$)			1,527.00	1,075.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >