

ASS. REC. BY:

Steve

REF:

CC3/11120098723/ba3

~~CS/ICS20099642/13~~

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SD22211K

Yr Regn:

24/6/19

Type ☒ M.Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

BMW 3301

c.c

1998

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

7212

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBASR120X7AK73114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD ARim or

Tyre Size:

F:

185 RSC

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/8/19

D.O.I.

10/9/20

Survey held at

Efficient Mph

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FM RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-183K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Formed:

Lump Sum / U.C. /

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Survey & repair
on 10/09 @ 10am-11am

Steve (LKK) wil per
83228813 10/9/20, 12 Mon
1 day
P/P, Ry Det sm

GST REG. NO : M2 - 0020081 - X

20 AUG 2020

ESTIMATE

Page No. : 1 of 4

Estimate No. : b1 55803
Date Estimated : 20/08/2020
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Hon Thiam Heng Jason
75A Redhill Road
#22-58

Singapore 151075

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDZ2211K	WBA5R120X0AK73114	24/06/2019	330i LIM	0

DESCRIPTION

To replace left side mirror assembly.

850 1,275.00

To painting left mirror cover.

75.00

To check electrical wiring systems

150 177.00

Sundries.

40.00

Total Labour 1: 1,567.00

DESCRIPTION

LH OUTSIDE MIRROR COVER CAP PRIMED X R

QTY PRIC VALUE

1 128.10 128.10

LH HEATED OUTSIDE MIRROR OR

1 962.85 962.85

LH AUXILIARY MIRROR TURN INDICATOR X NN

1 65.25 65.25

Total Parts : 1,156.20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To ☒ LKK Auto Consultants part(s) during resurvey
- To ☒ LKK Auto Consultants subject to confirmation
- To ☒ LKK Auto Consultants on a "Without Prejudice" basis
- No ☒ LKK Auto Consultants (s) is allowed
- No ☒ LKK Auto Consultants (s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1 : 1,567.00

Parts : 1,156.20

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 190.62

Grand Total : 2,913.82

Acknowledged by Repairer

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **