



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1493X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	SCRATCHED	175.00	130.00
1	FRONT WHEEL SHAFT	BENT	75.00	75.00
1	FRONT DISK BRAKE	WARPED	175.00	120.00
1	FRONT LEFT FORK ASSY	DEFORMED	680.00	520.00
1	FRONT RIGHT FORK ASSY	DEFORMED	680.00	520.00
1	STEERING STEM	BENT	220.00	220.00
1	STEERING BRIDGE	SCRATCHED	195.00	195.00
2	STEERING BEARINGS	NECESSARY	90.00	90.00
1	SET STEERING BRIDGE HOLDER	SERVICEABLE	150.00	-
1	FRONT LEFT SIGNAL	SCRATCHED	145.00	100.00
1	LEFT VIEW MIRROR	SCRATCHED	95.00	95.00
1	IU BRACKET	DEFORMED	75.00	75.00
1	HANDLE BAR	BENT	175.00	140.00
1	LEFT BALANCER	BENT	48.00	48.00
1	FRONT HEADLAMP	SCRATCHED	290.00	290.00
1	FRONT HEADLAMP COVER	SCRATCHED	105.00	105.00
1	FUEL TANK LEFT COVER	NOT NECESSARY	295.00	-
1	RADIATOR	DEFORMED	385.00	385.00
1	REAR SWING ARM	NOT NECESSARY	485.00	-
1	RADIATOR FAN ASSY (ADDITIONAL)	JAMMED	245.00	190.00
1	LEFT INNER COVER (ADDITIONAL)	DEFORMED	95.00	95.00
1	METER BRACKET (ADDITIONAL)	BENT	145.00	145.00
1	LEFT SWITCH ASSY (ADDITIONAL)	SCRATCHED	175.00	120.00
	LESS 10% DISCOUNT		-519.80	-365.80
			4,678.20	3,292.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SPORT RIM FRONT (SN)	TO REPAIR SEE LABOUR	580.00	-
1	COOLANT (SN)	NECESSARY	50.00	30.00
1	BOX RACK (SN)	DEFORMED	195.00	195.00
1	TOP CASE (SN)	SCRATCHED	250.00	250.00

Report Ref No. CC4/FCI20008728/Nes3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HANDPHONE HOLDER (SN) (ADDITIONAL)	DEFORMED	48.00	30.00
			1,123.00	505.00
	<b><u>LABOUR</u></b>			
	TOWING CHARGES .	NOT NECESSARY	100.00	-
	TO KNOCK ,STRAIGHTEN CHASSIS & BODY BALANCING .	NOT NECESSARY	380.00	-
	TO REMOVE /REFIT ,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.		180.00	80.00
	LABOUR TO REPAIR FRONT RIM.		150.00	150.00
	SPRAY PAINTING.		280.00	150.00
	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGED PARTS ,CHECK WIRING AND LIGHTING SYSTEM.INCLUSIVE OF THE REPAIR OF SPORT RIM FRONT .		800.00	300.00
			1,890.00	680.00
<b>GRAND TOTAL</b>			<b>7,691.20</b>	<b>4,477.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CC4/FCI20008728/Nes3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.