

(08/11/13) wef
ASS. REC. BY: *Marcus*

REF: *CS/SMO20008729/U+3*

ASSIGNMENT

From: Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GBA3761M*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Report Format :

Lum Sum / I.B.I. (\$

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp.Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NA / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185/6 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No work modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sompo Insurance Singapore Pte. Ltd

05-01/06 Land Tower

Raffles Place

Singapore 048623

Attn: Motor Claims Dept.

Estimate cost of repair vehicle no: GBA3761M

Tailgate

300500 ✓

\$1817.30 ✓

2pcs Tailgate Absorber

378-20x2 2x X

756-40 X

Tailgate emblem Logo

rec

61.30 ✓

Taillamp L/h

11

378.20 X

Conner panel L/h

2x

178.30 X

Rear bumper

252 ✓ 500, S.N

380.10 ✓

190.05 S.N

S/net items

Rear windscreen sealant

rec

60.00 40

70km sticker

rec

20.00 10

Reverse Sensor

NT X

280.00 X

Labor for knocking, cutting, welding, replace of parts

800.00 300

To spray paint on damage Portion

1000.00 300

To apply rust-proofing on the replaced portion

80.00 30

To renew rear windscreen glass

150.00 120

To remove/transfer tailgate components

150.00 50

To dismantle/ renew Reverse Sensor

100.00 X

Not Audited

2/5 1950/

3 days

Wh photo after rep

P-1878-60

259

P-1408-85

S-N-240.05

L-800

2449

22

1959