



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2005927
INV Date 28/08/2020
Reference CS/SMO20008729/Utf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. GBA 3761M
Insured Veh. GBJ 1357M
Claim No. CMTD2002415/MYE
Policy No.
Accident Date 15/08/2020
Inspection Date 20/08/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20008729/Utf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 28-08-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 1357M	Veh. Inspected	GBA 3761M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002415/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	KDH2000063070	Colour	SILVER	
Odometer	386940	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2020	Inspection Date	20/08/2020	
Survey held at	CHENG MOTOR WORK CO. NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 3761M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BADLY DENTED	1,817.30	1,817.30
2	TAILGATE ABSORBER @\$378.20	NOT NECESSARY	756.40	-
1	TAILGATE EMBLEM LOGO	NECESSARY	61.30	61.30
1	TAILLAMP L/H	NOT NECESSARY	378.20	-
1	CONNER PANEL L/H	TO REPAIR SEE LABOUR	178.30	-
	LESS 25% DISCOUNT		-	-469.65
			3,191.50	1,408.95
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER (50%)(SN)	DEFORMED	380.10	190.05
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	70KM STICKER (SN)	NECESSARY	20.00	10.00
1	REVERSE SENSOR (SN)	NOT FITTED	280.00	-
			740.10	240.05
	<u>LABOUR</u>			
	LABOR FOR KNOCKING,CUTTING,WELDING ,REPLACE OF PARTS.INCLUSIVE OF THE REPAIR OF CONNER PANEL L/H.		800.00	300.00
	TO SPRAY PAINT ON DAMAGE PORTION.		1,000.00	300.00
	TO APPLY RUST-PROOFING ON THE REPLACED PORTION.		80.00	30.00
	TO RENEW REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE/TRANSFER TAILGATE COMPONENTS.		150.00	50.00
	TO DISMANTLE/RENEW REVERSE SENSOR.	NOT NECESSARY	100.00	-
	-		-	-
	-		-	-
	-		-	-
			2,280.00	800.00
	GRAND TOTAL		6,211.60	2,449.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00

Report Ref No. CS/SMO20008729/Utf3n2



Report Ref No. CS/SMO20008729/Utf3n2

A handwritten signature in black ink, appearing to read 'Chua' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 3761M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 3761M

RE-INSPECTION

