

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008734/T1BS3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SDG8710Y	Insured Vehicle No :	SHD6813R
Date of Loss: 09/08/2020	Nature of Claim: TP	Claim No: MCT20080116

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDG8710Y		
Make & Model:	PORSCHE BOXSTER, TIPTRONIC (A)	Engine No:	65102589
Reg. Date:	05/01/2001 (Man. Year: 2000)	Chassis No:	WPOZZZ98Z1S600433
Colour:	Silver	Odometer:	40073 km
Engine Capacity:	2687 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,678.04	3,225.80	4,452.24	57.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,180.00	9,430.00	4,750.00	33.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,858.04	12,655.80	9,202.24	42.10
+ GST 7.00/7.00% (\$\$)	1,530.06	885.91	644.15	42.10
Nett Amount (\$\$)	23,388.10	13,541.71	9,846.39	42.10
+ Loss of Use (8.0 x S\$180.00/day) (\$\$)		1,440.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		14,989.16		

INSPECTION

Date of Assignment:	20/08/2020	
Date Inspected:	21/08/2020	Inspected At:
		Stuttgart Auto Pte Ltd (HQ)
		27A Tanjong Penjuru
		Singapore 609042
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2020)	
Parts:	N/A	PORSCHE BOXSTER TIPTRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG8710Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	1,225.40 FL	*1,225.40 FL
2	10		*SPEED NUT	Necessary	17.60 FL	*17.60 FL
3	1		*FRONT LH FENDER COVER	Not Necessary	20.90 FL	*- FL
4	3		*RIVET	Necessary	4.80 FL	*4.80 FL
5	1		*RPOTECTOR FILM RH	Necessary	20.20 FL	*20.20 FL
6	1		*FRONT RH FENDER STRUT BAR	Not Necessary	68.80 FL	*- FL
7	1		*FRONT FENDER BRACKET	Not Necessary	28.20 FL	*- FL
8	6		*HEXAGON NUT	Necessary	9.60 FL	*9.60 FL
9	1		*FRONT BUMPER	Repair	1,917.00 FL	*- FL
10	1		*FRONT BUMPER TOWING COVER	Not Necessary	37.40 FL	*- FL
11	1		*FRONT BUMPER RETAINER RH	Not Necessary	113.20 FL	*- FL
12	1		*BRACKET -RETAINING STRIP FRT BPR RH	Not Necessary	92.90 FL	*- FL
13	1		*RHS MIRROR HOUSING	Cracked	242.20 FL	*242.20 FL
14	1		*MIRROR BASE RIGHT ELECTRIC	Not Necessary	633.90 FL	*- FL
15	1		*TRIM SIDE MIRROR RH	Cracked	22.40 FL	*22.40 FL
16	1		*MIRROR ADJUSTING MOTOR	Jammed	329.00 FL	*329.00 FL
17	1		*FILLER PIECE OUTER RH	Not Necessary	35.10 FL	*- FL
18	1		*FILLER PIECE INNER RH	Not Necessary	24.60 FL	*- FL
19	1		*MIRROR GLASS (6678)	Not Necessary	272.40 FL	*- FL
20	1		*FRONT RH SIGNAL LIGHT	Cut	128.60 FL	*128.60 FL
21	1		*SHOCK ABSORBER RH	Not Necessary	1,495.00 FL	*- FL
22	1		*FRT ABSORBER STOPPER	Not Necessary	60.10 FL	*- FL
23	1		*DEEP -GROOVE BALL BEARING W	Not Necessary	114.10 FL	*- FL
24	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
25	1		*FRONT FENDER WHEEL ARCH RH	Deformed	738.50 FL	*738.50 FL
26	1		*HINGE ,FUEL CAP LID	Cracked	42.70 FL	*42.70 FL
27	1		*PETROL FILLER NECK BRACKET	Deformed	781.00 FL	*781.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,525.60	3,582.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	847.56	356.20
Total Parts (\$\$)	7,678.04	3,225.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /INSTALL FRT BUMPER ,FRT FENDER RH ,RH SIDE MIRROR & ALL ACCIDENT DAMAGED BODY PARTS .TO REPAIR FRONT DOOR RH & ALL AREAS AFFECTED BY THE ACCIDENT	New	6,240.00	4,680.00
2	TO RESPRAY FRT BUMPER ,FRT FENDER RH ,FRT DOOR RH ,RH SIDE MIRROR RH	New	4,600.00	3,750.00
3	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	200.00
4	TO REMOVE & REPLACE THE FRONT SUSPENSION RH	New	1,560.00	0.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	680.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (\$\$)			14,180.00	9,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >