

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008742/UES3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994023

Claimant

Vehicle No : FBR2724M

Insured Vehicle No : SJH7503J

Date of Loss: 07/08/2020

Nature of Claim: TP

Claim No: 7287311721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBR2724M

Make & Model: YAMAHA CZD300A / XMAX300, 292cc

Engine No: H336E0078551

Reg. Date: 25/03/2020 (Man. Year: 2020)

Chassis No: MH3SH0849LK010447

Colour: Green

Odometer: 6962 km

Engine Capacity: 292 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Rear Tyre Size: 140/70-14

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,991.80	3,643.30	3,348.50	47.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	385.00	925.00	70.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,301.80	4,028.30	4,273.50	51.48
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	8,301.80	3,200.00	5,101.80	61.45
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		3,320.00		

INSPECTION

Date of Assignment: 20/08/2020

Date Inspected: 20/08/2020 **Inspected At:**

EROFIA TRADING PTE LTD (HQ)

1 KAKI BUKIT AVE 6 # 02-62

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Repair	980.00 FL	*- FL
2	1		*WINDSHIELD	Cracked	248.00 FL	*248.00 FL
3	1		*HEADLAMP	Not Necessary	550.00 FL	*- FL
4	1		*SIDE MIRROR -L/H	Cracked	120.00 FL	*105.00 FL
5	1		*HANDLE-BAR	Bent	135.00 FL	*135.00 FL
6	1		*SET HANDLE-BAR BALANCER	Cut	80.00 FL	*80.00 FL
7	1		*BRAKE LEVER -L/H	Cut	104.00 FL	*104.00 FL
8	1		*FRONT COWLING INNER PANEL -L/H	Cracked	150.00 FL	*135.00 FL
9	1		*FRONT SIGNAL -L/H	Not Necessary	150.00 FL	*- FL
10	1		*LAMP STAY	Not Necessary	225.00 FL	*- FL
11	2		*LOWER BELLY PANELS	Cut	500.00 FL	*500.00 FL
12	2		*LOWER COWLING CENTRE GRILLES	Cut	200.00 FL	*200.00 FL
13	2		*FOOTSTEP PANELS	Cut	310.00 FL	*310.00 FL
14	1		*REAR HANDLE -L/H	Cut	85.00 FL	*85.00 FL
15	1		*ENGINE COVER	Not Necessary	350.00 FL	*- FL
16	1		*AIR FILTER BOX COVER	Cut	150.00 FL	*145.00 FL
17	1		*MAIN STAND	Cut	145.00 FL	*145.00 FL
18	1		*SET FAIRING COVER	Cracked	1,150.00 FL	*1,150.00 FL
19	1		*METER ASSY	Not Necessary	850.00 FL	*- FL
20	1		*FRONT SIDE COVER	O/S Cut	480.00 FL	*230.00 FL
21	1		*METER LOWER COVER	Not Necessary	120.00 FL	*- FL
22	1		*METER TOP COVER	Cracked	280.00 FL	*165.00 FL
23	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
24	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
25	1		*X MAX EMBLEM	Necessary	60.00 FS	*60.00 FS
26	1		*REAR BOX	Cut	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,728.00	4,017.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	736.20	373.70
Total Parts (\$\$)	6,991.80	3,643.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	350.00
4	TO RESPRAY PAINTING	New	800.00	0.00
Gross Labour Cost (\$\$)			1,310.00	385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >