

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008743/EQF3E2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999993854
Claimant Vehicle No : SCM66G	Insured Vehicle No : GBG1578H
Date of Loss: 17/08/2020	Nature of Claim: TP Claim No: 8905538599SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCM66G		
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Engine No:	2AZJ014987
Reg. Date:	05/06/2014 (Man. Year: 2013)	Chassis No:	ACR500165914
Colour:	Black	Odometer:	80101 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/08/2020	
Date Inspected:	21/08/2020 Inspected At:	Tri King Auto Solutions (HQ) 53 Paya Ubi Industrial Park, #01-15 Ubi Avenue 1 S(408934) Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*REAR BUMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*- F
9	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
10	1		*TAILGATE	Dented	0.00 F	*- F
11	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE GARNISH	Broken	0.00 F	*- F
13	3		*TAILGATE LAMP	Broken	0.00 F	*- F
14	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >