

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008750/T1GS3Q2

**Date:** 28/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900103878

**Claimant**  
**Vehicle No :** SHA3206D **Insured Vehicle No :** SLQ454S

Date of Loss: 19/08/2020 Nature of Claim: TP Claim No: 4343598628SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3206D		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2C17487
Reg. Date:	15/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU703080622
Colour:	Blue	Odometer:	160919 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	490.67	115.75	374.92	76.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	520.00	80.00	13.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,090.67</b>	<b>635.75</b>	<b>454.92</b>	<b>41.71</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	76.35	44.50	31.85	41.72
<b>Nett Amount (\$\$)</b>	<b>1,167.02</b>	<b>680.25</b>	<b>486.77</b>	<b>41.71</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (\$\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$126.47/day) (\$\$)</b>		252.94		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,035.19</b>		

### INSPECTION

Date of Assignment: 20/08/2020

Date Inspected: 20/08/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NO PLATE	Bent	25.00 FS	*25.00 FS
2	1		*BRACKET FRT BUMPER	Cracked	99.00 FL	*99.00 FL
3	1		*COVER FRONT BUMPER	Repair	499.90 FL	*- FL
4	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
					<b>Sub Total (S\$)</b>	<b>645.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>155.23</b>
					<b>Total Parts (S\$)</b>	<b>490.67</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

**146.00**

**30.25**

**115.75**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>600.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**