



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7329U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP LH (CONSISTENT)	CRACKED	1,850.40	1,850.40
1	FRONT HEADLAMP LOWER BUMPER RETAINER (CONSISTENT)	CRACKED	35.00	35.00
1	FRONT BUMPER (CONSISTENT)	DENTED	459.80	459.80
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	BENT	15.70	15.70
1	FRONT BUMPER FOG LAMP GRILLE (CONSISTENT)	DEFORMED / TWISTED	45.00	45.00
1	FRONT BUMPER FOG LAMP LH (CONSISTENT)	CRACKED	327.40	327.40
1	FRONT BUMPER LOWER SPOILER (CONSISTENT)	NOT NECESSARY	351.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	321.80	321.80
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	385.00	-
1	FRONT GRILLE BASE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	351.80	-
1	FRONT FENDER WHEEL ARCH GARNISH (CONSISTENT)	TORN	153.00	153.00
	LESS 20% DISCOUNT		-859.18	-641.62
			3,436.72	2,566.48
	<b><u>LABOUR</u></b>			
	REMOVE & INSTALL F/GRILLE ,F/HEADLAMP,F/BUMPER,BUMPER LOWER SPOILER ,F/FENDER WHEEL ARCH ,KNOCK F/FENDER ,HEADLAMP SUPPORT PANEL AN RESTRAIGHTEN BODY & CHASSOS.		700.00	500.00
	SPRAY PAINTING .		800.00	550.00
	CHECK WIRING SYSTEM.		25.00	25.00
			1,525.00	1,075.00
<b>GRAND TOTAL</b>			<b>4,961.72</b>	<b>3,641.48</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CC4/ASM20008754/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.