

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008760/AGA3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800110137

Claimant
Vehicle No : SMR5429R **Insured Vehicle No :** SKX9089D

Date of Loss: 17/08/2020 Nature of Claim: TP Claim No: 8127705072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR5429R	Engine No:	A3190989L8GX0006
Make & Model:	OPEL ASTRA, 4DR 1.6 PREMIUM (A)	Chassis No:	W0VBD8EG3K8047227
Reg. Date:	13/01/2020 (Man. Year: 2019)	Odometer:	62271 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,459.75	7,351.80	5,107.95	41.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,685.00	3,230.00	3,455.00	51.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	19,144.75	10,581.80	8,562.95	44.73
+ GST 7.00/7.00% (\$\$)	1,340.13	740.73	599.40	44.73
Nett Amount (\$\$)	20,484.88	11,322.53	9,162.35	44.73
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		11,524.53		

INSPECTION

Date of Assignment: 19/08/2020

Date Inspected: 19/08/2020 Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,110.00 FL	*2,110.00 FL
2	1		*REAR TAILGATE OPEL LOGO	Necessary	71.00 FL	*71.00 FL
3	1		*LETTERING ASTRA	Necessary	71.00 FL	*71.00 FL
4	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	883.00 FL	*- FL
5	1		*REAR TAILGATE WEATHERSTRIP	Cut	190.00 FL	*190.00 FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	461.00 FL	*461.00 FL
7	1		*LHR TAILGATE LAMP	Not Necessary	476.00 FL	*- FL
8	1		*RHR TAILGATE LAMP	Not Necessary	476.00 FL	*- FL
9	1		*LHR TAILLAMP	Not Necessary	901.00 FL	*- FL
10	1		*RHR TAILLAMP	Not Necessary	901.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,653.00 FL	*1,653.00 FL
12	1		*REAR BUMPER TOWING COVER	Deformed	118.00 FL	*118.00 FL
13	1		*REAR BUMPER SILL PLATE	Deformed	496.00 FL	*496.00 FL
14	1		*LHR BUMPER REFLECTOR	Cracked	120.00 FL	*120.00 FL
15	1		*RHR BUMPER REFLECTOR	Not Necessary	120.00 FL	*- FL
16	1		*LHR BUMPER BRACKET ,GUIDE	Cracked	91.00 FL	*91.00 FL
17	1		*RHR BUMPER BRACKET ,GUIDE	Cracked	91.00 FL	*91.00 FL
18	1		*LHR BUMPER BRACKET	Cracked	45.00 FL	*45.00 FL
19	1		*RHR BUMPER BRACKET	Cracked	45.00 FL	*45.00 FL
20	1		*REAR BUMPER CENTRE BRACKET	Cracked	89.00 FL	*89.00 FL
21	1		*REAR BUMPER ABSORBER	Cracked	256.00 FL	*256.00 FL
22	1		*REAR BUMPER REINFORCEMENT BAR	Bent	771.00 FL	*771.00 FL
23	1		*REAR END PANEL ,LOWER	Repair	686.00 FL	*- FL
24	1		*PANEL ,REAR LOWER	Repair	628.00 FL	*- FL
25	8		*REAR END PANEL TRIM INCLUDE CLIPS	Not Necessary	52.00 FL	*- FL
26	1		*REVERSE SENSOR WIRING HARNESS	Snapped	441.00 FL	*441.00 FL
27	1		*SET REVERSE SENSOR	Damaged	440.00 FL	*440.00 FL
28	1		*SET SEAL ,REVERSE SENSOR	Necessary	60.00 FL	*60.00 FL
29	1		*SET REAR BUMPER CLIP (10 PCS)	Necessary	65.00 FL	*30.00 FL
30	5		*REAR END PANEL TRIM CLIP (1 SET)	Not Necessary	32.50 FL	*- FL
31	10		*TAIL GATE INNER TRM BOARD CLIP (1 SET)	Necessary	65.00 FL	*30.00 FL
32	1		*REAR NUMBER PLATE WITH BRACKET	Not Necessary	45.00 FS	*- FS
33	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
35	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	180.00 FS	*- FS
36	1		*RR TAILGATE HONDS FREE SENSOR	Cracked	423.00 FL	*423.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,792.50	8,162.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,332.75	810.20
Total Parts (\$\$)	12,459.75	7,351.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,250.00	1,300.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	2,500.00	1,500.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	130.00	40.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	65.00	30.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	130.00	60.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	130.00	60.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	260.00	120.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	100.00	0.00
9	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			6,685.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >