

## Re: Mechanical Inspection Report Request

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>

**Sent:** Wednesday, 19 August 2020 11:37 AM

**To:** Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

**Cc:** Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Raziz TAHAR (SPF) <Raziz\_TAHAR@spf.gov.sg>; Syed Muhammad FARID ALBAR (SPF) <Syed\_Muhammad\_FARID\_ALBAR@spf.gov.sg>; Adrian LIM (SPF) <Adrian\_LIM@spf.gov.sg>; Muhammad Rizwan KAMALUDIN (SPF) <Muhammad\_Rizwan\_KAMALUDIN@spf.gov.sg>

**Subject:** Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 5 vehicles below: **[The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS].**

a. Case IAFP-IB-20200819 - Mechanical Inspection of Motorcycle, JSM6419 (TP/IP/27727/2020)

b. Case IAFP-IB-20200819 - Mechanical Inspection of Motorcar, SKZ7483B (TP/IP/27727/2020)

On 29 June 2020 Friday at 1.26 a.m., the Deceased (who was alone on his motorcycle JSM 6419) was travelling along Jalan Kebun Limau towards Balestier Road when he self-skidded and encroached into the travel path of motorcar SKZ 7483 B which was travelling straight along Balestier Road towards Lavender Street on lane 2 of 3-lane road. The front portion of the motorcar subsequently collided into the said motorcycle. As a result of the accident, the Deceased sustained head injuries and succumbed to his injuries. He was pronounced dead at the accident scene.

**Vehicle to be inspected:** JSM6419 - Rider (Deceased)  
SKZ7483B - Driver (Involved Party)

IO In-Charge: SIO Raziz

c. Case IAFP-IB-20200819 - Mechanical Inspection of Prime Mover, XE2046U (TP/IP/29993/2020)

On 16 July 2020 at about 2.35 p.m., the prime mover was travelling along Jurong Island Highway towards end. Approaching the signalised cross junction of Ayer Merbau Road, the driver claimed he proceeded across the stop line on amber traffic light signal. At the junction, the driver felt an impact coming from his left to right perspective therefore he immediately swerved to the right and applied brakes. As such, this vehicle has to undergo a thorough mechanical inspection by an external expert to rule out the possibility of any mechanical fault.

**Vehicles to be inspected:** XE2046U - Driver (Potential Defendant)

IO In-Charge: IO Syed Albar

d. Case IAFP-IB-20200819 - Mechanical Inspection of Motorcycle, FBG7058C (TP/IP/33933/2020)

On 11 August 2020 sometime before 6.08 p.m., the accused was riding his motorcycle along Xilin Avenue into ECP(MCE). While negotiating the left bend at the slip road, accused suddenly lost control of his motorcycle and skidded to the right. Both accused and pillion (Deceased) were conveyed to CGH where the pillion succumbed to her injuries and was pronounced dead at CGH at 7.17 p.m.

**Vehicles to be inspected:** FBG7058C - Rider (Potential Defendant)

IO In-Charge: SIO Adrian Lim

e. Case IAFP-IB-20200819 - Mechanical Inspection of Motorcar, SLB5250J (TP/IP/33657/2020)

On 10 August 2020 sometime before 1.12 a.m., the accused was driving his motorcar along Piccadilly Road when he claimed seeing an unknown object running across the road. To avoid a collision, the accused swayed to the right and mounted the right kerbside, almost entering into the drainage area. The accused claimed that a group of passer-by assisted him and sent him home, leaving his motorcar unattended and abandoned along Piccadilly Road. CTP is aware of this case and directed for IO to conduct a thorough mechanical inspection on the motorcar before releasing it to the owner.

**Vehicles to be inspected:** SLB5250J - Driver (Potential Defendant)